



2-FCF-994




2-FCF-994 · FR 1,0L TSI 110HP DSG KJ75RZ E05 · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FCF-994	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ6RR116687
Model	Arona	Cylinder Capacity	999 ^{cm³}
Model Versions	FR 1,0L TSI 110HP DSG KJ75RZ E05	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	22-03-2024
Color	Black	Odometer	74.896 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	85	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	4 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	2 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	4 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	Compressor					

Damages



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Left	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Left	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Scratch(es)	Spray	No



Damage Part
Fender - Front Left

Damage Type
Small dent(s)

Repair Type
Restyle / Touch-up

Acceptable
No



Damage Part
Hood

Damage Type
Stonechipping

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Overfender

Damage Type
Scratch(es)

Repair Type
Replace

Acceptable
No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Front	Scratch(es)	Sierkapje	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Small dent(s)	Plastic Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Scratch(es)	Spray	No



Damage Part
Bumper - Rear

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No




Damage Part
Tailgate

Damage Type
Small scratch(es)

Repair Type
Polish

Acceptable
No



Damage Part
Interior

Damage Type
Stains & dirt

Repair Type
Cleaning

Acceptable
No