

INSPECTION REPORT

End of contract

GENERAL INFO

File	316244
License plate	2AXY654
Vehicle identification number	TMAJB81AAMJ096079
Dossier	2021 145 096
Make	Hyundai Tuc.CRD 85kW Inspire
Mileage	74354
First registration	02/09/2021
client availability date	25/06/2026
inspectionDate	08/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
183	Wing Rear Right // Painting	N
13	Bumper Front // Painting	N
28	Front / Calendar / Replace	Y
72	Side View Mirror Left // Painting	Y
77	Side View Mirror Left / Shell / Replace Not Painted	Y
84	Door Front Left // Repair & Painting	Y
92	Rocker Panel Left // Painting	Y
100	Door Rear Left // Smart Repair Small	Y
107	Door Rear Left / Trim / Replace	Y
116	Wing Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
150	Rear Bonnet // Smart Repair Small	N
158	Rear Bonnet / 3rd Stoplight / Replace	Y
161	Roof // Smart Repair Medium	Y
196	Door Rear Right // Polish	Y
214	Door Front Right // Repair & Painting	Y
233	Wing Front right // Painting	Y
281	Bumper Rear / Trim Left / Replace	Y
314	Wheel Front Left / Wheel Cover / Replace	N
342	Wheel Alloy Front Right // Replace	N
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
641	Rear Right Door Interior Coating // Repair	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	Y

Damage Pictures



Door Rear Right // Polish-scratch



Door Rear Left // Smart Repair Small-scratch



Door Rear Left / Trim / Replace-scratch



Rocker Panel Left // Painting-scratch



Wing Rear Left // Polish-scratch




Rear Bonnet / 3rd Stoplight / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch




Rear Bonnet // Smart Repair Small-dent



Roof // Smart Repair Medium-dent




Door Front Right // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent




Interior // Repair 1-Incinerated



Trunk Compartment / Boot Cover / Replace-missing



Interior Cleaning // Small-stain



Key Price Range 2 //-worn



Wheel Alloy Front Right // Replace-scratch



Wing Front right // Painting-scratch



Front / Calendar / Replace-scratch




Bumper Front // Painting-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch



Side View Mirror Left // Painting-scratch



Bumper Rear / Trim Left / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Wing Rear Right // Painting-scratch