



**CITROËN Berlingo: 9504-MFY**

Vinnumber:	<b>VR7EFYHT2NN575492</b>	Versionname:	<b>Citroen Talla M BlueHdi 100 S&amp;S LIVE PACK BUSINE combi 75kW 4P manual</b>
First Registrationdate:	<b>31/03/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>103326</b>	Power Kw:	
Bodytype:	<b>Transporter</b>	Body colour:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Steel</b>
Transmission:			
Fueltype:	<b>Diesel</b>		
Engine functioning:	<b>Yes</b>		
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Steel</b>		
Certificate of Conformity:	<b>No</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Central consol F
Number keys remote	<b>2</b>	Luggage cover
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of climate control	<b>Manual climate control</b>	

**Tyres**

<b>205/60/16/96 V</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 0 mm</b>	Fr.R.	<b>Goodyear: 0 mm</b>
	Re.L.	<b>Bridgestone: 0 mm</b>	Re.R.	<b>Bridgestone: 0 mm</b>
Tyre size FL				<b>205/60 R 16 96 V</b>
Tyre size FR				<b>205/60 R 16 96 V</b>
Tyre size RL				<b>205/60 R 16 96 V</b>
Tyre size RR				<b>205/60 R 16 96 V</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>255</b>
Tyre make RR				<b>255</b>

**Assistance equipment**

Repair kit	<b>No</b>
------------	-----------

Interior, Damaged, Check





Interior, Dirty, Cleaning



MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Wheel cover RL, Scratch(es), Acceptable



Wheel cover FR, Missing, Replace



Wheel cover RR, Missing, Replace



Tyre repair kit, Missing, Repair/replace (lump sum)



Tyres, No damage, Check



