MACADAM









VOLVO XC60: FR-875-EW

Vinnumber:	**LYVUZBMVDLB602712**	Versionname:	**VOLVO XC60 T8 Twin Engine 390 GT 8 Inscription Luxe VP [5P] bva 8-390CH-17cv (SUV)**
First Registrationdate:	**7/07/2020**	Fiscalpower:	
Expertise Mileage:	**999999**	Power Kw:	**287**
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Plug-in hybrid**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Seats electric F L	
GPS big screen color		Seats electric F R	
GPS storage		Sun Roof electric	
GPS storage	**HD**	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Seats F heated		Rear view camera	
Type of climate control	**Autom climate control**	Seat cover lining	**Lining Leather**

Tyres

Summer tyres:	**235/55/19/105 V**			
	Fr.L.	**Michelin: 35%**	Fr.R.	**Michelin: 40%**
	Re.L.	**Michelin: 40%**	Re.R.	**Michelin: 35%**

Tyre profile depth FL	**5.9**
Tyre profile depth FR	**5.5**
Tyre profile depth RL	**5.6**
Tyre profile depth RR	**5.8**
Tyre size FL	**235/55 R 19 105 V**
Tyre size FR	**235/55 R 19 105 V**
Tyre size RL	**235/55 R 19 105 V**
Tyre size RR	**235/55 R 19 105 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Instrument panel cover, Broken, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)








Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)






Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)






Headlight L, Crack, Replace




Door RR, Dent(s), Acceptable




Door FR, Dent(s), Acceptable




Bumper R, Scratch(es), Polish




ALPHABET

Historique Maintenance

Immatriculation: **FR-875-EW** Date de 1ère immatriculation: **07/07/2020**

Modèle: **Volvo XC60 T8 Twin Engine 390 GT 8 Inscription Luxe VP [5P] bva 8-390CH-17cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
30/06/2026	84.835	FELIX FAURE AUTOMOBILES*	RECYCLAGE
30/06/2026	84.835	FELIX FAURE AUTOMOBILES*	REMPLACEMENT PNEUS 4 SAISONS
28/05/2026	83.604	FELIX FAURE AUTOMOBILES*	REVISION ET CLIM ET AIR ET BOUGIES
			LIQUIDE DE FREIN
			ESSAI
			BALAIS ESSUIE GLACE AV AR
			BALAIS ESSUIE GLACE AV AR
			PLAQUETTES AR RPLT
			PLAQUETTES AV RPLT
			RECYCLAGE
07/05/2025	66.843	CENTRE DE CONTROLE TECHNIQUE AUTOMOBILE DE CORBAS	CONTROLE TECHNIQUE
09/10/2024	57.687	FELIX FAURE AUTOMOBILES*	REVISION
			RECYCLAGE
07/02/2024	48.170	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
31/08/2023	42.578	EUROFLEET TYRES AND SERVICES	REPARATION DE ROUE
26/04/2023	35.043	FELIX FAURE AUTO VAISE	REVISION ET CLIM ET AIR ET BOUGIES
			BALAIS ESSUIE GLACE AV AR
			LIQUIDE DE FREIN
25/04/2023	35.014	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
			PERMUTATIONS PNEUS
20/01/2023	32.144	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
			PERMUTATIONS PNEUS
22/04/2022	21.685	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE
			GARDIENNAGE
			PERMUTATIONS PNEUS
03/12/2021	17.885	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER
02/12/2021	17.205	FELIX FAURE AUTOMOBILES*	FILTRE CLIM RPLT
			REVISION
28/12/2020	4.720	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE