



Volkswagen ID.4: L952NX

Vinnnumber:	WVGZZZE2ZMP038379	Versionname:	ID 4 150kW / 77kWh Life Aut.
First Registrationdate:	11/08/2021	Fiscalpower:	
Expertise Mileage:	108920	Power Kw:	150
Bodytype:		Body colour	Mangan Grey metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	850
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
GPS		Hook
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 30 / 19 / 107 / W / Aluminium	3,5 mm	Hankook	Summer
	Right	255 / 30 / 19 / 107 / W / Aluminium	4,6 mm	Hankook	Summer
Rear	Left	255 / 30 / 19 / 107 / W / Aluminium	4,5 mm	Hankook	Summer
	Right	255 / 30 / 19 / 107 / W / Aluminium	4,6 mm	Hankook	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
Door FL, Scratch(es), Repair and paint (complete)	



Bonnet, Chemical polution, Polish



Fuel cap cover, Broken, Replace and paint



Wing RR, Scratch(es), Polish



Door RR, Scratch(es), Polish




Wing FR, Chemical polution, Polish



Bumper corner RR, Scratch(es), Polish



Roof, Chemical polution, Repair and paint (complete)



Kenteken	L952NX
Merk Model	Volkswagen ID 4 150kW / 77kWh Life Aut.
Brandstofsoort	Elektrisch
Datum deel1	11-08-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
21-08-25	88.409	Airco CO2 vulling
21-08-25	88.409	APK
21-08-25	88.409	Onderhoudsbeurt
21-08-25	88.409	Ruitenwisherblad(en) achterzijde
21-08-25	88.409	Ruitenwisherblad(en) voorzijde
21-08-25	88.409	Sleutelbatterij
21-08-25	88.409	Vervanging band
21-03-25	77.102	Reparatie band(en)
02-03-25	0	Accu
23-08-24	62.868	Vervanging band
03-06-24	50.000	Reparatie band(en)
16-06-23	33.012	Airco reinigen
16-06-23	33.012	Ruitenwisherblad(en) voorzijde
16-06-23	33.012	Sleutelbatterij