APPRAISAL REPORT



IDENTIFICATION VEHICLE

Make:	AUDI
Model / version:	Q3
Vin:	WAUZZZF32P1026720
Plate:	2CLR759
Mileage:	72367
SOH:	
First registration:	07/09/2022
Color:	Mythoszwart





ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	✓

DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	?

PICTURES














































VIN INFORMATION

Radio avec système de navigation	Transmission séquentielle	6 rapports
Projecteurs à allumage automatique	Matière : alliage	Lettre repère (J)
Diamètre avant 17	Diamètre arrière 17	Largeur avant 7,0
Largeur arrière 7,0	Diamètre avant 17	Diamètre arrière 17
Hauteur avant 65	Hauteur arrière 65	Indice de vitesse avant H
Indice de vitesse arrière H	Largeur avant 215	Largeur arrière 215
Climatisation automatique	Climatisation réfrigérant 1234YF	Accoudoir central avant
Ordinateur de bord	Euro 6	Effet perle vernissée
Freins avant à disques	Freins arrière à disques	Rétroviseur droit convexe
Rétroviseur gauche asphérique	Garnitures tissu	Volant cuir
Volant multifonction	Aide au stationnement avant	Aide au stationnement arrière
Caméra avant	Régulateur et limiteur de vitesse	Equipement Stop & Start

Affichage lecture des panneaux de signalisation	Verrouillage centralisé à commande à distance	Ouverture du coffre électriquement
Appel de secours	détecteur de pluie essuie-vitre	Airbag passager
Airbag passager désactivable	Prétensionneurs de ceintures avant	Freinage d'urgence assistée autonome (urbain)
Avertisseur d'angle mort	depuis 07.22	radio avec récepteur numérique
câble de charge pour station de recharge publique Mode 3 Type 2 3 (16A)	1395 cc (1,4 L) 110 KW (essence) / 180 KW (Total)	réservoir à charbon actif (EVAP)
Audi Drive Select	porte-bagages pavillon noir	transmission hybride PHEV

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		215/65R17 99V	Summer	Aluminium	×
Front right	5 mm		215/65R17 99V	Summer	Aluminium	×
Rear left	5 mm		215/65R17 99V	Summer	Aluminium	×
Rear right	5 mm		215/65R17 99V	Summer	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot lid covering R	Grooved
2	Bumper R	Grooved
3	Wing RR	Dent(s)
4	Contact key - Contactsleutel niet functioneel meer	Damaged
5	Door RL	Grooved
7	Tailgate / Boot	Dent(s) and scratch(es)

Total: 6

ACCEPTABLE / NOT TO BE INVOICED


#	Location	Damage type	Renta®	Repaired	Already invoiced
6	Bodywork	Scratch(es)	✓	×	×

Total: 1



DAMAGES DETAILS

1 - Boot lid covering R - Grooved








2 - Bumper R - Grooved
















3 - Wing RR - Dent(s)





4 - Contact key - Contactsleutel niet functioneel meer - Damaged


5 - Door RL - Grooved






7 - Tailgate / Boot - Dent(s) and scratch(es)






6 - Bodywork - Scratch(es) - Renta®






SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

14/10/2026 15:22

