



PEUGEOT 308: GF-713-JL

Vinnumber:	VR3FBYHZTNY521122	Versionname:	PEUGEOT 308 BlueHDI 130 AUTO8 ALLURE PACK VP [5P] bva 8-130CH-7cv (bi-corps)
First Registrationdate:	23/03/2022	Fiscalpower:	
Expertise Mileage:	69021	Power Kw:	96
Bodytype:	Berline	Body colour:	Green
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	
Type of climate control	Autom climate control	Lining Other	Lining Semi-leather

Tyres

225/45/17/94 W			
Summer tyres:	Fr.L.	Kleber: 45%	Fr.R.
	Re.L.	Kleber: 40%	Re.R.
			Kleber: 50%
			Kleber: 40%
Tyre profile depth FL			5.3
Tyre profile depth FR			5.0
Tyre profile depth RL			5.7
Tyre profile depth RR			5.5
Tyre size FL			225/45 R 17 94 W
Tyre size FR			225/45 R 17 94 W
Tyre size RL			225/45 R 17 94 W
Tyre size RR			225/45 R 17 94 W
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			2479
Tyre make FR			2479
Tyre make RL			2479
Tyre make RR			2479

Assistance equipment

Interior, Dirty, Cleaning





Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GF-713-JL** Date de 1ère immatriculation: **23/03/2022**
Modèle: **Peugeot 308 BlueHDI 130 AUTO8 ALLURE PACK VP [5P] bva 8-130CH-7cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
03/03/2026	63.852	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
23/06/2025	52.537	GARAGE DU STADE	PLAQUETTES AV RPLT
	0		REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV AR
22/01/2025	43.403	GARAGE DU STADE	RESERVOIR ADBLUE RPLT
22/05/2024	33.053	GARAGE DU STADE	BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM
	0		LIQUIDE DE FREIN
24/04/2024	31.758	EUROMASTER FRANCE	REMPLACEMENT PNEUS ETE
04/05/2023	17.219	IMMO AIX	RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM