



**VOLKSWAGEN PASSAT:**

Vinnumber:	<b>WVWZZZ3CZME095611</b>	Versionname:	<b>1.4 TSI GTE Business DSG</b>
First Registrationdate:	<b>11/03/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>87745</b>	Power Kw:	
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2201</b>
Fueltype:	<b>Hybrid Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>Tow bar collapsible</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Tyres**

<b>215/55/17/94 V</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 2 mm</b>	Fr.R.	<b>Pirelli: 2 mm</b>
	Re.L.	<b>Pirelli: 4 mm</b>	Re.R.	<b>Pirelli: 4 mm</b>
Tyre profile depth FL				<b>2.0</b>
Tyre profile depth FR				<b>2.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>215/55 R 17 94 V</b>
Tyre size FR				<b>215/55 R 17 94 V</b>
Tyre size RL				<b>215/55 R 17 94 V</b>
Tyre size RR				<b>215/55 R 17 94 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>264</b>
Tyre make FR				<b>264</b>
Tyre make RL				<b>264</b>
Tyre make RR				<b>264</b>

**Assistance equipment**

Number of charging cables (normal):	<b>0</b>	Runflat:	<b>Yes</b>
Number of charging cables (rapid charge):	<b>1</b>		

Total cost ex VAT	911,76
Interior, Damaged, Acceptable	0,00



Door panel FL, Broken, Forfeit 25,50



Bumper F, Scratch(es), Repair and paint (complete) 296,58



Bumper moulding F, Scratch(es), Repair and paint (complete) 161,81



Wing FL, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Wing RL, Dent(s), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03





Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete) 161,81



Door RR, Scratch(es), Acceptable 0,00



Step R, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03



Roof, Dent(s) and scratch(es), Acceptable 0,00



Roof, Chemical polution, Polish 0,00



Bodywork, Not original part, Remove lettering 0,00

