



MERCEDES C BREAK: [REDACTED]

Vinnumber:	W1K2052131G082218	Versionname:	C 300 de Business Solution Auto
First Registrationdate:	11/02/2021	Fiscalpower:	
Expertise Mileage:	161171	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2414
Fueltype:	Hybrid Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar collapsible
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

245/40/18/97 V				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				245/40 R 18 97 V
Tyre size FR				245/40 R 18 97 V
Tyre size RL				245/40 R 18 97 V
Tyre size RR				245/40 R 18 97 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	1	
Number of charging cables (rapid charge)	1	

Total cost ex VAT	1001,58
Bumper F, Dent(s) and scratch(es), Repair and paint (complete)	296,58



Bonnet, Stone chip(s), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Door FR, Scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21

