



CITROËN C3: 5556-LXN

| | | | |
|------------------------------------|--------------------------|-------------------------|--|
| Vinnumber: | VF7SXYHTUNT538741 | Versionname: | Citroen BlueHdi 75KW (100CV) S&S Feel berlina con portón 75kW 5P manual |
| First Registrationdate: | 28/04/2022 | Fiscalpower: | |
| Expertise Mileage: | 125423 | Power Kw: | |
| Bodytype: | Berline | Body colour: | White |
| Gearbox: | MAN 6 VIT | Type of rims (mounted): | Steel |
| Transmission: | | | |
| Fueltype: | Diesel | | |
| Battery functioning: | No | | |
| Vehicle running: | No | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Type of rims (mounted): | Steel | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | |
|--------------------------------|------------------------------|---------------|
| Number of keys total | 1 | Luggage cover |
| Number keys remote | 0 | |
| Windows electric F | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of climate control | Autom climate control | |

Tyres

| | | | | |
|-----------------------|-------|-----------------------|-------|-------------------------|
| 205/55/16/94 V | | | | |
| Summer tyres: | Fr.L. | Goodyear: 4 mm | Fr.R. | Goodyear: 4 mm |
| | Re.L. | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |
| Tyre profile depth FL | | | | 4.0 |
| Tyre profile depth FR | | | | 4.0 |
| Tyre profile depth RL | | | | 5.0 |
| Tyre profile depth RR | | | | 5.0 |
| Tyre size FL | | | | 205/55 R 16 94 V |
| Tyre size FR | | | | 205/55 R 16 94 V |
| Tyre size RL | | | | 205/55 R 16 94 V |
| Tyre size RR | | | | 205/55 R 16 94 V |
| Tyre make FL | | | | 259 |
| Tyre make FR | | | | 259 |
| Tyre make RL | | | | 259 |
| Tyre make RR | | | | 259 |

Assistance equipment

| | |
|----------------------------------|------------|
| Repair kit | Yes |
| Interior, Dirty, Cleaning | |





Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Engine, Not functioning (well), Check



Boot lid covering R, Scratch(es), Acceptable



Door FL, Scratch(es), Repair and paint (complete)



Wheel cover FL, Scratch(es), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Wheel cover FR, Scratch(es), Acceptable



Bumper moulding R, Crack, Repair and paint (complete)



Bumper R, Scratch(es), Acceptable



Tyres, No damage, Check

