



BMW X1: N374NT

Vinnumber:	WBA71AB0905U55783	Versionname:	X1 xDrive 25eA 162kW
First Registrationdate:	30/11/2021	Fiscalpower:	
Expertise Mileage:	166156	Power Kw:	92
Bodytype:		Body colour	Mineralgrau Metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	435
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 50 / 18 / 99 / W / Aluminium	4,1 mm	Bridgestone	Summer
	Right	225 / 50 / 18 / 99 / W / Aluminium	4,2 mm	Bridgestone	Summer
Rear	Left	225 / 50 / 18 / 99 / W / Aluminium	4,6 mm	Bridgestone	Summer
	Right	225 / 50 / 18 / 99 / W / Aluminium	4,4 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
Door RL, Scratch(es), Repair and paint (complete)	



Alloy rim FL, Scratch(es), Repair and paint (complete)



Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Check



Kenteken	N374NT
Merk Model	BMW X1 xDrive 25eA 162kW
Brandstofsoort	Benzine
Datum deel1	30-11-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
29-05-26	161.981	Bobine
29-05-26	161.981	Bougie
29-05-26	161.981	Olie service
29-05-26	161.981	Onderhoudsbeurt
01-12-25	146.751	APK
26-08-24	115.231	Olie service
26-08-24	115.231	Remvloeistof
26-08-24	115.231	Ruitenwischerblad(en) achterzijde
28-08-23	75.808	Bougie
28-08-23	75.808	Luchtfilter
28-08-23	75.808	Olie service
28-08-23	75.808	Onderhoudsbeurt
28-08-23	75.808	Ruitenwischerblad(en) voorzijde
22-08-22	37.049	Olie service
22-08-22	37.049	Sleutelbatterij