



2022 PORSCHE MACAN

Vehicle reference:

WP1ZZZ95ZNLB02305

Body type:

Estate

Gearbox type:

Automatic

Engine size:

1984 cm³

Fuel type:

Petrol

Combustion engine power:

195 kW / 265 hp

Drive:

AWD

Quick check



Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.



Import

Not a private import

Legend



No issues reported or indicated



Valuable Information



Requires attention




Data unavailable

Damage overview

05/2023

Affected area (1):

Location reference, does not indicate the extent of the damage.



Reported in
Italy

Damage
type/cause
Not available

Damage severity:




Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

03/2024

Affected area (1):

Location reference, does not indicate the extent of the damage.



Reported in
Italy

Damage
type/cause
Not available

Damage severity:




Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

07/2024

Affected area (1):

Location reference, does not indicate the extent of the damage.



Reported in
Italy

Damage type/cause
Collision with another vehicle

Damage severity:




Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

06/2025

Affected area (1):

Location reference, does not indicate the extent of the damage.



Reported in
Italy

Damage type/cause
Not available

Damage severity:




Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

08/2025

Affected area (1):

Location reference, does not indicate the extent of the damage.



Front

 Reported in
Italy

 Damage
type/cause
Not available

Damage severity:



Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

Recommended maintenance

Default schedule

Provided by CARFAX Europe



Vehicle age

4 years, 9 months

Routine maintenance is essential for preserving a vehicle's reliability.

Critical past due service tasks

These service tasks are expected based on the vehicle age. Verify if they were completed.

Before buying, ask the seller:

- Are service records available?
- Were the following services performed?

 **Engine oil and oil filter** **due 4 times**
Change every year

 **Brake fluid** **due 2 times**
Change every 2 years

Costly upcoming service tasks

Before buying, confirm whether:

- Any of the upcoming maintenance tasks are already completed.
- You've accounted for related costs in your future budget.

 **Brake discs and pads**
Inspect yearly, replace as needed

 **Tires**
Inspect yearly, replace as needed

CARFAX tips



Keeping up with scheduled servicing is a strong indicator that the vehicle has been well cared for and is in good overall condition.



Owner(s) in Italy

Purchase year: 2021

Damage reported on: 08/2025 , 06/2025 , 07/2024 , 03/2024 , 05/2023

Technical details

Engine and performance

Fuel type

Petrol

Combustion engine power

195 kW / 265 hp

Environment and consumption

CO2 emissions in mixed driving

244 g/km



Fuel consumption in mixed driving

10.8 l/100km

EU emission standard

Euro 6

Weight

Curb weight

1 920 kg

Max payload

590 kg

Gross vehicle weight

2 510 kg

Dimensions

Length

4 726 mm

Width

1 922 mm

Wheelbase

2 807 mm

Other information

European vehicle category

M1

EU standard code

e13*2007/46*1165*20

Number of doors

5

Number of seats

5

History information

Date

Mileage

Event

2021-10-18

Registered in Italy

05/2023

Damage reported in Italy

03/2024

Damage reported in Italy

07/2024

Damage reported in Italy

06/2025

Damage reported in Italy

08/2025

Damage reported in Italy

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

CARFAX Glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Model year

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

| How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions](#).