




## 2-EUS-957



2-EUS-957 · 116iA Business Edition · 22 June 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-EUS-957	Fuel Type	Gasoline
Manufacturer	BMW	VIN	WBA7K110407P07300
Model	1-serie	Cylinder Capacity	1.499 <sup>cm<sup>3</sup></sup>
Model Versions	116iA Business Edition	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	02-02-2024
Color	Black	Odometer	73.379 <sup>km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	80	Number Headrests	5

Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Roller cover / parcel shelf

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate


Last Maintenance Unknown

Previous Repairs Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 <sup>mm</sup>	Bridgestone	205 <sup>mm</sup>	55 <sup>mm</sup>	16 <sup>inch</sup>	Summer
Rear Left	5 <sup>mm</sup>	Bridgestone	205 <sup>mm</sup>	55 <sup>mm</sup>	16 <sup>inch</sup>	Summer
Front Right	4 <sup>mm</sup>	Bridgestone	205 <sup>mm</sup>	55 <sup>mm</sup>	16 <sup>inch</sup>	Summer
Rear Right	5 <sup>mm</sup>	Bridgestone	205 <sup>mm</sup>	55 <sup>mm</sup>	16 <sup>inch</sup>	Summer
Spare Tire Type	None					

## Damages



Damage Part

Fender - Front Left

Damage Type


Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Alloy - Left Front

Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Hood

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Front

Damaged

Rim repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Right

small dents / small scratches

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Right

Scratch(es)

Panelbeating & Spray

No




Damage Part  
Bumper - Rear

Damage Type  
Small scratch(es)

Repair Type  
Touch-up / Polish

Acceptable  
No



Damage Part  
Tailgate

Damage Type  
Scratch(es)

Repair Type  
Spray

Acceptable  
No




Damage Part  
Roof

Damage Type  
Scratch(es)

Repair Type  
Spray

Acceptable  
No



Damage Part

Interior

Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No