

# INSPECTION REPORT

**End of contract**

## GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 312872                         |
| License plate                 | 2GME677                        |
| Vehicle identification number | VR7ACYHZXRL027521              |
| Dossier                       | 2023355209                     |
| Make                          | Citroen C5 Aircr.1.5BHDi 130 P |
| Mileage                       | 17673                          |
| First registration            | 27/01/2025                     |
| client availability date      | 13/05/2026                     |
| inspectionDate                | 19/05/2026                     |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                            | Acceptable |
|---------|-------------------------------------------------|------------|
| 32      | Front Bonnet // Painting                        | N          |
| 83      | Door Front Left // Painting                     | Y          |
| 106     | Door Rear Left // Polish                        | Y          |
| 117     | Wing Rear Left / Trim / Replace                 | N          |
| 131     | Bumper Rear // Smart Repair Medium              | Y          |
| 138     | Bumper Rear / Lower Cover Not Painted / Replace | Y          |
| 156     | Rear Bonnet // Polish                           | Y          |
| 187     | Wing Rear Right / Trim / Replace                | N          |
| 196     | Door Rear Right // Polish                       | Y          |
| 197     | Door Rear Right / Trim / Replace                | N          |
| 233     | Wing Front right // Painting                    | Y          |

## Damage Pictures



Front Bonnet // Painting-scratch



Wing Front right // Painting-scratch



Door Rear Right // Polish-scratch




Door Rear Right / Trim / Replace-scratch



Wing Rear Right / Trim / Replace-scratch



Rear Bonnet // Polish-scratch



Bumper Rear // Smart Repair Medium-scratch






Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Door Rear Left // Polish-scratch



Door Front Left // Painting-scratch