MACADAM








ALFA ROMEO Stelvio: 6951-MKM

Vinnumber:	**ZARPAGPX9P7D76391**	Versionname:	**2.2 Diesel 118kW (160CV) SPRINT RWD todoterreno 118kW 5P automática**
First Registrationdate:	**26/09/2023**	Fiscalpower:	
Expertise Mileage:	**117082**	Power Kw:	
Bodytype:	**SUV**	Body colour	**Dark Grey**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**No**		
Battery functioning	**No**		
Vehicle running	**No**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**No**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**1**	Central consol F	
Number keys remote	**1**	Front parking sensors	
Type of climate control	**Autom climate control**	Rear parking sensors	

Tyres

Summer tyres:	**235/55/19/105 W**			
	Fr.L.	**Continental: 5 mm**	Fr.R.	**Continental: 5 mm**
	Re.L.	**Continental: 5 mm**	Re.R.	**Continental: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**235/55 R 19 105 W**
Tyre size FR	**235/55 R 19 105 W**
Tyre size RL	**235/55 R 19 105 W**
Tyre size RR	**235/55 R 19 105 W**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Registration document, Missing, Repair/replace (lump sum)




Ignition key, Missing, Repair/replace (lump sum)




MOT certificate, Missing, Repair/replace (lump sum)




Door FL, Scratch(es), Repair and paint (complete)




Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Wing RL, Dent(s) and scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)






Wing RR, Dent(s), Repair and paint (complete)




Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Bumper R, Scratch(es), Repair and paint (complete)





Bumper moulding R, Scratch(es), Repair and paint (complete)




Tyres, No damage, Check






Bodywork, Damaged, Check


