


VOLKSWAGEN TOURAN:

Vinnumber:	WVGZZZ1TZLW022264	Versionname:	1.5 TSi Trendline DSG
First Registrationdate:	9/01/2020	Fiscalpower:	
Expertise Mileage:	93547	Power Kw:	110
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Steel
Transmission:		Parking lot	2627
Fueltype:	Petrol		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection
Tyres

205/60/16/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Falken: 5 mm	Re.R.	Falken: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/60 R 16 92 H
Tyre size FR				205/60 R 16 92 H
Tyre size RL				205/60 R 16 92 H
Tyre size RR				205/60 R 16 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				1957074
Tyre make RR				1957074

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	608,67
Door panel RL, Scratch(es), Acceptable	0,00



Bumper F, Scratch(es), Spot repair

148,33



Windscreen, Scratch(es), Polish

0,00



Wheel cover FL, Scratch(es), Acceptable

40,94



Door FL, Dent(s), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Wheel cover RL, Scratch(es), Acceptable

40,94



Bumper R, Scratch(es), Repair and paint (complete)

296,58



Rear window, Scratch(es), Acceptable

0,00



Wheel cover RR, Scratch(es), Acceptable

40,94



Wheel cover FR, Scratch(es), Acceptable	40,94
---	-------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing RR, Bad repair, Check	0,00
----------------------------	------

