



IDENTIFICATION VEHICLE

Driver name:
Make: PEUGEOT
Model / version: 308 SW
Vin: VR3FRHNSLPY557506
Plate: 2DTV562
Mileage: 83427
First registration: 22/06/2023
Color:



ADDITIONAL INFORMATION







Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

depuis 01.23 16855

avertisseur à deux tons

liquide de climatisation R1234YF

rétroviseur int jour/nuit automatique

6 haut-parleurs

aide au parking ar

volant en cuir multifonctions

1199 cc (1,2 L) 96 KW HNS EB2ADTS

suspension normale

barre stabilisatrice av 27.500 Nm

7 J x 16 Alu "Auckland"

ventilateur électrique 95 W

batterie 70 Ah EFBC

3-ème période 2021/avant 3-ème période 2023

climatisation automatique

Keyless-Go

avertisseur de fatigue

instruments digitaux

garnissage tissu

Peugeot Connect Assistance

radiateur de 28 dm² et de 18 mm

d'épaisseur "F1"

système de freinage automatique avec caméra et radar (AEBS3)

disques de frein av 304 mm

7 J x 16 Alu

norme anti-pollution Euro 6.4

2 couches nacrée

3-ème période 2022/avant 3-ème période 2024

condenseur de 19,3 dm² et de 12 mm d'épaisseur

rétroviseurs électrique, rabattables et chauffants

système de navigation

Touchscreen 10"

équipement Active

sièges av Confort

6 vitesses MB6

colonne de direction réglable en profondeur

205/55 R 16 .. V

alternateur 150 A

5 portes (Wagon)

EQUIPMENT

Board computer:



Compressor:



Gps:



Rear parking sensor:



Central locking:



Cruise control:



Power steering:



Repair kit:



Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm			All-seasons		?
Front right	4 mm			All-seasons		?
Rear left	4 mm			All-seasons		?
Rear right	4 mm			All-seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Seat cover RL	Hole
3	Door FL	Dent(s) and scratch(es)
4	Alloy rim RL polished	Grooved
5	Roof - +-46deuken	Hail damage
6	Wing RR	Scratch(es)
7	Alloy rim RR polished	Grooved
8	Outside rear-view mirror housing R	Scratch(es)
9	Alloy rim FR polished	Grooved
10	Rear window	Scratch(es)

Total: 9

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Seat cover RL - Hole




3 - Door FL - Dent(s) and scratch(es)



4 - Alloy rim RL polished - Grooved



5 - Roof - +46deuken - Hail damage



6 - Wing RR - Scratch(es)




7 - Alloy rim RR polished - Grooved



8 - Outside rear-view mirror housing R - Scratch(es)



9 - Alloy rim FR polished - Grooved



10 - Rear window - Scratch(es)



2 - Bodywork - Dent(s) and scratch(es) - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

04/09/2026 11:21