



BMW 3 Reeks (K1): 2BSL580

Vinnnumber:	WBA6N31070FM65476	Versionname:	330e Touring (G21) 2.0i 292pk/cv 5p Aut.
First Registrationdate:	8/03/2022	Fiscalpower:	
Expertise Mileage:	109738	Power Kw:	135
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	25000 km - 02/2028		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/40/19/93 Y			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/40 R 19 93 Y
Tyre size FR				255/35 R 19 96 Y
Tyre size RL				255/35 R 19 96 Y
Tyre size RR				225/40 R 19 93 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	1		

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Acceptable



Windscreen, Stone chip(s), Replace



Alloy rim FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s), Repair and paint (complete)



Boot lid covering R, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Paintless dent repair



Alloy rim RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Kenteken	2BSL580
Merk Model	BMW 330e Touring (G21) 2.0i 292pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	3/8/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/24/26	100,976	BMW/MINI service standaard omvang	Uitvoeren
2/24/26	100,976	klein materiaal	
2/24/26	100,976	koelwatervloeistof	Bijvullen/-laden
2/24/26	100,976	nazicht technische keuring	Uitvoeren
2/24/26	100,976	ruitenswisserrubber achter	Vervangen
2/24/26	100,976	ruitenswisserrubber vooraan	Vervangen
2/24/26	100,976	ruitenswisservloeistof	Bijvullen/-laden
2/24/26	100,976	service microfilter	Uitvoeren
2/24/26	100,976	service motorolie	Uitvoeren
12/23/24	69,117	BMW/MINI service standaard omvang	Uitvoeren
12/23/24	69,117	BMW/MINI service voertuig-check	Uitvoeren
12/23/24	69,117	bougie	Vervangen
12/23/24	69,117	remvloeistof	Vervangen
12/23/24	69,117	service luchtfilter	Uitvoeren
12/23/24	69,117	service microfilter	Uitvoeren
12/23/24	69,117	service motorolie	Uitvoeren
2/9/24	45,109	batterij	Vervangen
9/26/23	36,786	controle niveaus	Uitvoeren
9/26/23	36,786	service microfilter	Uitvoeren
9/26/23	36,786	service motorolie	Uitvoeren
12/21/22	16,351	controle niveaus	Uitvoeren