



Polestar 2:

Vinnumber:	YSMVSEDE1PL117182	Versionname:	
First Registrationdate:	18/10/2022	Fiscalpower:	
Expertise Mileage:	169046	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1127
Fueltype:	Electric		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar collapsible
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

245/40/20/92 H				
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/40 R 20 92 H
Tyre size FR				245/40 R 20 92 H
Tyre size RL				245/40 R 20 92 H
Tyre size RR				245/40 R 20 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	1864,71
-------------------	----------------

Seat cover FL, Stain, Cleaning	29,16
--------------------------------	--------------



Seat cover FR, Stain, Cleaning 29,16



Wing RL, Dent(s), Acceptable 0,00



Tyre RL, Tear, Replace 211,22



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Bumper R, Scratch(es), Repair and paint (complete) 355,89




Tyre FR polished, Scratch(es), Repair and paint (complete) 211,22



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Tyre RR, Tear, Replace 211,22



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21

