



Renault Master:

Vinnumber:	VF1MA000862409468	Versionname:	
First Registrationdate:	29/01/2019	Fiscalpower:	
Expertise Mileage:	183410	Power Kw:	
Bodytype:		Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:		Parking lot	Icv26
Fueltype:	Diesel		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Tyres

tyres

	225/65/16/92 H			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/65 R 16 92 H
Tyre size FR				225/65 R 16 92 H
Tyre size RL				225/65 R 16 92 H
Tyre size RR				225/65 R 16 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				265
Tyre make FR				265
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1371,12
-------------------	---------

Ignition key, Missing, Replace	262,56
--------------------------------	--------



Steering wheel, Worn, Acceptable	0,00
----------------------------------	------



Air vent, mid-dashboard, Broken, Replace

60,23



Seat cover FR, Stain, Cleaning

29,16



Seat cover FL, Stain, Cleaning

29,16



Interior, Damaged, Acceptable

0,00



Bumper F, Scratch(es), Smart repair

116,69



Wheel cover FL, Scratch(es), Acceptable

0,00



Outer sill L, Scratch(es), Acceptable

0,00




Door FL, Dent(s), Acceptable

0,00



Wheel cover RL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Replace

365,14




Boot moulding, Scratch(es), Acceptable	0,00
--	------



Rear door panel RL, Bad repair, Check	0,00
---------------------------------------	------



Wheel cover FR, Scratch(es), Replace	44,82
--------------------------------------	-------



Door RR, Scratch(es), Repair and paint (complete)	334,34
---	--------




Door trim RR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Wing trim RR, Scratch(es), Replace	104,39
------------------------------------	--------




Wheel cover RR, Scratch(es), Acceptable	0,00
---	------



Door RR, Dent(s), Acceptable	0,00
------------------------------	------



Bodywork, Not original part, Remove lettering	0,00
---	------



Bodywork, Damaged, Replace	24,63
----------------------------	-------

