APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	RENAULT
Model / version:	ARKANA
Vin:	VF1RJL008UC324595
Plate:	2CNM632
Mileage:	126561
SOH:	
First registration:	27/09/2022
Color:	Noir d'Ivoir



ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	1
Original key:	✓


PICTURES





































VIN INFORMATION

depuis 02.22	série supplémentaire (ENPH01)	climatisation automatique (CA02)
vitres latérales et lunette ar teintées foncé (VSTLAR)	liquide de climatisation R1234yf (1234Y)	commande à distance 433 MHz (SOP03C)
rétroviseurs électrique chauffants et rabattables automatique (RET04)	capteur d'angle mort (DANGMO)	système d'appel d'urgence (RCALL/PCALL)
appareil de commande TCU (AIVCT)	feux de jour LED 3 (FDIU3)	essuie-glace avec allumage automatique des feux (ALEVA)
feux de route et de croisement automatique (PRAHL)	sièges av Type N 05 (SGAV05)	avertisseur de trafic latéral (RCTA0)
volant en mousse 1 (VLMOU1)	tableau de bord numérique (MET04)	bruit de véhicule pour piétons (VSPTA)
architecture électronique (AVC1A)	aide au parking av et ar (ITPK4)	caméra de marche arrière (RRCAM)
norme anti-pollution Euro 6d (E06U)	1598 cc (1,6 L) 69/70 KW LDMU 105/119 KW (Total)	équipement supplémentaire (SAN913)
4 vitesses automatique DB1	Full Hybrid (HYB05)	gestion de la vitesse (AVOSP1)
frein à main électrique (FPASS/FPAS2)	assistant de trajectoire (DLIGM2)	régulateur de vitesse (RV)
215/60 R 17 .. H	7 J x 17 Alu "BAHAMAS" (RALU17^RDIF03)	roue de secours temporaire (RSGALT)
système de freinage d'urgence (AEBS07)	code équipement (EA2)	2 couches métallisée

EQUIPMENT

Board computer: ?

Central locking: ?

Compressor:		**Cruise control:**	
Gps:		**Power steering:**	
Rear parking sensor:		**Repair kit:**	
Front seats heated:		**Steering wheel:**	
Electric windows:		**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:		**Fast charging cables:**	

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm			Summer	Aluminium	
Front right	4 mm			Summer	Aluminium	
Rear left	4 mm			Summer	Aluminium	
Rear right	4 mm			Summer	Aluminium	

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key	Missing
3	Inner door sill FL	Dent(s) and scratch(es)
4	Inner door sill RR	Dent(s)
5	Alloy rim FR	Scratch(es)

Total: 4

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Contact key - Missing



3 - Inner door sill FL - Dent(s) and scratch(es)







4 - Inner door sill RR - Dent(s)




5 - Alloy rim FR - Scratch(es)





2 - Bodywork - Dent(s) and scratch(es) - Renta®










SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

13/10/2026 08:39

