


Vehicle details

VIN	WVGZZZE2Z NP000547	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate		Model	ID.4 77kWh Business Auto 5d	Maintenance mileage	-
Registration date	29/11/2021	Year	2021	Exterior Color	Blue Metallic
Odometer	122 787 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date 04/06/2026



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
Vehicle charger	✓





Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓


Tyres

Hankook 235/55/19 Summer 3.0 mm			Hankook 235/55/19 Summer 3.0 mm	
Hankook 255/50/19 Summer 3.5 mm			Hankook 255/50/19 Summer 3.5 mm	

Exterior

<p>2</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 19"</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 19"	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 19"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 19"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Alloy wheel 19"																						
Position	Front left																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Alloy wheel 19"																						
Position	Front right																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
<p>4</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Dent & Chips	Severity	Diameter (mm) > 20	Repair mode	Repair	<p>5</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Roof	Position	-	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Repair
Part	Bonnet																						
Position	-																						
Damages	Dent & Chips																						
Severity	Diameter (mm) > 20																						
Repair mode	Repair																						
Part	Roof																						
Position	-																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Repair																						

Others

<p>1</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Wireless charger</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Wireless charger	Position	-	Damages	Missing	Severity	-	Repair mode	For info
Part	Wireless charger										
Position	-										
Damages	Missing										
Severity	-										
Repair mode	For info										