Opel Combo 102pk Closed van L1H1 Airco Navi Carplay Camera Trekhaak Euro6 L1

W0VEFYHT2NJ819275 · lot Costs



VEHICLE DATA & SPECIFICATIONS

VIN	w0vefyht2nj819275
First Registration	1/31/2023
Country of Origin	Netherlands
Mileage	187,688 km
Opel Combo 102pk Closed va...	Lot: 35Veghel, NetherlandsFirst registration: January 31, 2023Mileage: 187,688 km102 hp
Front / Right	Back / Left
Place your bid	Auto-bid
Transport costs	Vehicle location:Veghel, NetherlandsCalculate delivery time and price
Vehicle location	
Engine Output HP/PK	102 hp
Power type	Diesel
Emission norm	Euro 6
Cilinder Amount	4
Distribution type	Belt
Engine displacement (cc)	1499
Engine Type	DV5RCF
Amount of Axles	2
Tyre size Axle 1	195/65 R15
Tyre Size Axle 2	195/65 R15
Undercarriage	Wheeled
Wheelbase	279 cm

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Tyre condition Axle 1 Left (MM)	3 mm
Tyre condition Axle 1 Right (M...	3 mm
Tyre condition Axle 2 Left (MM)	mm
Tyre condition Axle 2 Right (M...	mm
Rear view camera	Rear view
Type Lights	Halogen
Door opening height	112 cm
Door opening width	124 cm
Inner height	118 cm
Inner length	178 cm
Inner width	124 cm
Space between wheelarches	123 cm
Material floor	Wood
Van size	L1H1
Mileage	187688 km
Airco option	airco
Number of seats	2
Type of cabin	Single
Type of Radio	DAB
Empty weight	1446 kg
Registration Date	2023-01-31
Towing weight	1350 kg
M.O.T. approved till	2027-01-31
NAP	Logisch
Gross Vehicle Weight (GVW)	2020 kg
VIN / Serial Number/ Chassisn...	W0VEFYHT2NJ819275
Brand	Opel
Model	Combo
Product Group (Tax)	Closed Van
Axle capacity 1	1200 kg
Axle configuration	2002-10-04
Colour	white
Country of origin	NL
Type of drive	FWD
Type extended	Combo 102pk
Max load capacity	574 kg
Vehicle Height (cm)	179 cm
Vehicle Length (cm)	450 cm
Vehicle Width (cm)	167 cm
Request Transaction Id	0ac634da-8672-44af-aa62-1d4eddbc96ec
Amount of forward gears	6

VEHICLE DATA & SPECIFICATIONS - CONTINUED

Transmission	Manual
Truck ID	70341433
Lot	35
First registration	January 31, 2023
November 3, 2026 at 02	17 PM

Damage & Condition

All known damages are listed and shown in photos for full transparency.

1 damage reported | Worst: Minor




Unknown — Minor

Other

Towbar preperation



Front / Right



Back / Left




16°C
11:40
DAB 100% NL
11C
Band
DAB
Zender 1/14
538
3
4
5
6
7
OPTIES
Frequentie
Geheugen
Lijst
BRONNEN


16°C
100% NL
11:40
Telefoon koppelen
OPTIES
Contacten


16°C
100% NL
11:40
Zone niet in kaart gebracht
MENU
Zoeken...


Controleer de omgeving alvorens de manoeuvre uit te voeren


16°c
100% NL
11:40
Voor het verbeteren van deze functies kan informatie met betrekking tot autogegevens en autolocatie worden verzonden naar uw verbonden apparaat.
Apple CarPlay
Connected-apps
Android Auto
Connectiviteit


16°C
100% NL
11:40
Profiel deactiveren
Audio-instellingen
Scherm uit
Geen profiel
OPTIES
Profiel 1
Profiel 2
Profiel 3


16°C
100% NL
11:39
Stop and Start
OFF ON
Parkeerhulp
OFF ON
Antispinregeling
OFF ON
Bandenspan.contr.
Diagnose
Besturingsfuncties
Instellingen van de auto.


A/C




AUTO


AUTO


x1000/min
km/h
0 km/h
187689 km
609.3 km
CHECK
000


RES/+
SET/-


SRC


OPEL
OPEL COMBO
Gebruikershandleiding
OPEL COMBO
Handleiding Infotainment










AR


R
V


















16°C
11:48
DAB 100% NL
11C
OPTIES


16°C
100% NL
11:48
MENU
Zoeken...


16°C
11:48
Audio-instellingen
Scherm uit
Geen profiel
OPTIES
Profiel 1
Profiel 3




0 km/h


OPEL
OPEL COMBO
OPEL COMBO





