



Expertise

Protocol number: 46205233
Order No. / Reference: 26527558
Inspection date: 26 Jun 2026

Manufacturer: Mercedes-Benz
VIN: W1K5M8GB9PN342906

Model: CLA 250 e Shooting Brake 8G-DCT AMG Line



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz CLA 250 e Shooting Brake 8G-DCT AMG Line	
Vehicle Identification number	W1K5M8GB9PN342906
Mileage (Read)	111,519 km
First registration	23 Dec 2022
Number of holders	1
Next periodical technical inspection	12/2027
(Report not on hand)	
Power / Engine displacement	118 kw / 1,332 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufl / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Nachtschwarz
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	173 Tag(e)
Last service on / at	12/2025 at 95,461 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM936169
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / ASY 00097		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,270 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95Y	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	225/45 R18 95Y	Summer tyres on Light alloy	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	225/45 R18 95H	Winter tyres on Light alloy	Continental	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- ADAPTIVE BRAKE with HOLD function, hill start assist, pre-filling and drying brakes in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbag for driver and front passenger
- AMG floor mats
- AMG Styling
- Anti-lock braking system (ABS)
- Foldable armrest for driver and front passenger
- Basic services
- Double cup holder at the front
- Third brake light in LED technology
- ECO start/stop function
- Chassis: Comfort chassis
- electric parking brake
- Transmission: 8G-DCT automatic
- Black fabric headliner
- THERMATIC automatic climate control
- Front headrests, integrated
- Charging cable for household socket, 5m, smooth
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Mercedes-Benz emergency call system
- Otto particulate filter
- Package: Seating comfort
- Radio: MBUX multimedia system
- Radio accessories: Communication module (LTE) for using Mercedes me connect services
- Tire pressure monitoring system (TPMS)
- Gearshift lever in perforated Nappa leather and additional chrome elements
- Seat belts CLA-Class
- Seats: Rear seat backrests are split 40:20:40 and foldable
- Lane Keeping Assist, active
- Bumpers in body color
- Touchpad
- Electronic immobilizer
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Acoustic environmental protection
- AMG sports pedal assembly made of brushed stainless steel with rubber studs
- Traction control (ASR)
- ATTENTION ASSIST
- Brake assist, active
- Tachometer
- DYNAMIC SELECT
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Speed Limit Assistant
- Lockable glove compartment
- KEYLESS-GO start function
- Rear headrests (3)
- Paint finish: Solid
- Steering wheel shift paddles
- Steering: Direct steering
- Light and rain sensor
- Net in the passenger footwell
- Package: Light and Visibility Package
- Radio: Extended MBUX functions
- Radio accessories: Digital radio (DAB)
- Radio accessories: USB interface in the storage compartment & 2 USB interfaces in the rear center console
- Wheels: 45.7 cm (18") AMG light-alloy wheels, 4 in 5-twin-spoke design
- Windscreen wipers with rain sensor
- Seats: iSize child seat anchorages with top tether on the outer seats
- 12V power outlet
- Cruise control
- High-visibility vest for drivers
- Central locking



Extra equipment

- Airbag: Sidebags in the rear, left and right
- AMG Line 950
- GUARD 360° Vehicle Protection Plus (Break-in and theft warning - Towing protection with visual and audible warning upon detected change in position - Audible alarm - Interior monitoring (triggers upon movement inside the vehicle) - Assistance with vehicle theft (theft assistance), free for 3 years from activation - Emergency key deactivation, free for 3 years from activation - GUARD 360° label on the front side windows - Collision detection, free for 3 years from activation, additionally with camera images in conjunction with 360°)
- Package: Business for €250 (Hard drive navigation - Smartphone integration - Traffic sign assistant - Preparation for digital key handover - Connectivity package navigation - Seat heating for driver and front passenger - Active parking assistant with PARKTRONIC - Public charging package - Charging cable for wallbox and public charging stations, 5m, smooth - Remote and Charging Services Plus)
- Package: Leather package (leather seat covers - contrasting decorative stitching on the instrument panel)
- Package: MBUX High-End Package (Hard drive navigation - Pre-installation for Live Traffic Information - Traffic Sign Assist - Connectivity Package Navigation: Hard drive navigation, Extended Navigation Services - Smartphone Integration: Mobile phone via Apple CarPlay and Android Auto with the media system - Pre-installation for digital key handover - Wireless charging system for mobile devices or multifunction telephone - Central Media Display - Fully digital instrument display - MBUX Augmented Reality for navigation)
- Wheels: Run-flat tires
- Seats: 4-way lumbar support for driver and front passenger
- Heat-insulating dark tinted glass
- Decorative elements: aluminum with longitudinal brushing, light finish
- Ambient lighting with 64 different colors
- Towbar with ESP trailer stabilization (electrically folding towbar - switch with LED in the boot - LED indicates when the ball neck is not in a locked end position - ESP trailer stabilization)
- Charging system: AC charging system 7.4 kW
- LED High Performance headlights (The LED High Performance headlights offer greater safety at night and a distinctive, striking look. Thanks to LED technology, they illuminate the road better than conventional headlights – with lower energy consumption.)
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: Driving Assistance Package (Active Distance Assist DISTRONIC - Active Speed Limit Assist - Extended Automatic Restart on Highways - Route-Based Speed Adaptation with Traffic Jam Function - Active Steering Assist - Active Emergency Stop Assist with SOS Function - Emergency Lane Function - Active Brake Assist - Turning and Intersection Communication - Traffic Jam Emergency Brake Communication - Evasive Steering Assist - Active Lane Keeping Assist - Active Blind Spot Assist - Exit Warning Function - Pedestrian Warning in the Area of Crosswalks)
- Package: Parking package with reversing camera (including Active Parking Assist with PARKTRONIC - reversing camera)
- Package: Mirror package (interior and exterior mirrors on the driver's side automatically dimming - exterior mirrors left and right electrically folding)
- Radio accessories: Advanced sound system (with 10 speakers and 225 watts system power)
- Sunroof: Electric panoramic sunroof
- Partition net for luggage compartment separation and occupant protection

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
2	Wheel / tyres	Alloy rim - rear left side - Scratched - Loss in value



Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	2nd wheel set	Alloy rim set - complete (Kein Teil der Ausstattung) - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer	1.380,65 €
2	Front, Provided by user / customer	2.301,55 €
3	Side right, Provided by user / customer	5.083,35 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Comments

Die zusätzlichen Winterräder sind kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 1: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value




Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1K5M8GB9PN342906

Hersteller / Modell: MERCEDES-BENZ MB CLA 250 e Shooting Brake 8G-DCT AMG
Line

Datum	KM-Stand	Beschreibung
09.12.2025	95.461	AU; Regelwartungsdienst
16.04.2025	68.606	Systemtest/Eigendiagnose
15.01.2025	71.192	Regelwartungsdienst
17.04.2024	46.321	Regelwartungsdienst
15.06.2023	22.707	Regelwartungsdienst