



OPEL ASTRA SPORTS TOURER:

Vinnumber:	W0VBE8EVXL8026341	Versionname:	1.5 Turbo D 90kW S/S Ultimate
First Registrationdate:	4/05/2020	Fiscalpower:	
Expertise Mileage:	131893	Power Kw:	90
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2215
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

	225/45/17/91 H			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/45 R 17 91 H
Tyre size FR				225/45 R 17 91 H
Tyre size RL				225/45 R 17 91 H
Tyre size RR				225/45 R 17 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1833,57
Bonnet, Stone chip(s), Acceptable	0,00



Door FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Wing RL, Chemical pollution, Repair and paint (complete)

431,58



Bumper R, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Replace

594,70



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03



Roof, Chemical pollution, Repair and paint (complete)

674,26

