



RENAULT CLIO: GJ-226-JP

Vinnumber:	VF1RJA00868850154	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)
First Registrationdate:	12/09/2022	Fiscalpower:	
Expertise Mileage:	112622	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Rear parking sensors	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	195/55/16/91 H			
Summer tyres:	Fr.L.	Bridgestone: 45%	Fr.R.	Bridgestone: 50%
	Re.L.	Bridgestone: 25%	Re.R.	Bridgestone: 20%
Tyre profile depth FL	5.3			
Tyre profile depth FR	4.8			
Tyre profile depth RL	6.6			
Tyre profile depth RR	6.9			
Tyre size FL	195/55 R 16 91 H			
Tyre size FR	195/55 R 16 91 H			
Tyre size RL	195/55 R 16 91 H			
Tyre size RR	195/55 R 16 91 H			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	255			
Tyre make FR	255			
Tyre make RL	255			
Tyre make RR	255			

Assistance equipment

Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)	





Roof liner, Worn, Repair/replace (lump sum)



Door RL, Dent(s), Repair and paint (complete)



Bumper F, Broken, Replace and paint



Number plate F, Deformed / Strained, Repair/replace (lump sum)



Bonnet, Dent(s), Repair and paint (complete)



Wing RR, Scratch(es), Paint



Outer sill R, Dent(s), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Luggage compartment cover, Missing, Replace



Bumper R, Scratch(es), Paint



Bodywork, Not original part, Remove lettering



Historique Maintenance

Immatriculation: **GJ-226-JP** Date de 1ère immatriculation: **12/09/2022**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
30/03/2026	106.194	GARAGE LAVIGNASSE	BALAIS ESSUIE GLACE AV AR
	0		TELECHARGEMENT CALCULATEUR
	0		TELECHARGEMENT CALCULATEUR
	0		TELECHARGEMENT CALCULATEUR
	0		BALAIS ESSUIE GLACE AV AR
16/02/2026	102.403	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER
27/01/2026	100.961	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
27/01/2026	100.961	EUROFLEET TYRES AND SERVICES	GEOMETRIE CTRL
01/07/2025	84.284	SARL FIDALGO	REPARATION DE ROUE
01/07/2025	84.284	SARL FIDALGO	REVISION ET CLIM
09/12/2024	70.953	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER
08/08/2024	63.013	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
27/06/2024	59.741	SARL FIDALGO	REVISION ET CLIM ET AIR ET BOUGIES
10/08/2023	31.237	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS ETE
28/07/2023	30.077	SARL FIDALGO	PLAQUETTES AV RPLT
	0		REVISION ET CLIM