



BMW X1:

Vinnumber:	WBA31AC0905578312	Versionname:	sDrive16d (85 kW)
First Registrationdate:	3/12/2020	Fiscalpower:	
Expertise Mileage:	110836	Power Kw:	85
Bodytype:		Body colour	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1115
Fueltype:	Diesel		
Maintenance	NOT OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining artificial leather	Type of Tow bar	No Tow bar
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/50/18/92 H				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/50 R 18 92 H
Tyre size FR				225/50 R 18 92 H
Tyre size RL				225/50 R 18 92 H
Tyre size RR				225/50 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2341,20
Service, Maintenance, Check	0,00



Seat cover FL, Damaged, Acceptable	0,00
------------------------------------	------



Backrest cover FL, Scratch(es), Smart repair	116,69
--	--------



Bumper F, Chemical polution, Polish	0,00
-------------------------------------	------



Bonnet, Chemical polution, Repair and paint (complete)	406,19
--	--------



Step L, Scratch(es), Acceptable	0,00
---------------------------------	------



Wing RL, Dent(s), Acceptable	0,00
------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing trim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Bumper trim R, Scratch(es), Acceptable	0,00
--	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Rear window, Scratch(es), Replace	565,24
-----------------------------------	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Door FR, Dent(s) and scratch(es), Repair and paint (complete)	445,79
---	--------



Wing trim RR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Roof pillar R, Bad repair, Check	0,00
----------------------------------	------



Wing RR, Bad repair, Check	0,00
----------------------------	------



Roof, Chemical polution, Repair and paint (complete)	674,26
--	--------

