

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia				
				Policyholder				Opposite party				Opposite party company		
				Operation 2026		Claim number		Code / Agency				Date accident 30/06/2026		
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT		
Date assignment 30/06/2026		Date first survey 02/07/2026		Place Forli		C/O	Repairs		Photo	Lien in favor of				
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)										Formerly plate				
Lessee / Co-owner										Date of overhaul				
Vehicle (Brand - Model - Version) SKODA FABIA 1.0 MPI Evo 59KW YOUNG EDITION							Plate GY783HN		Vin Chassis TMBEE6PJ7S4038023		First Registration 06/02/2025			
Usage status NON CONOSCIUTO		Km 36317	Tyres % 50	Color Bianco		Type of enamel PASTEL/DOUBLE			Consistency of damage		Type of Expert's report NOT DEFINITIVE			
Equipment														
Approval code		For commercial vehicles	Carrying Qls 0	Tare, Q 0	Wheelbase	Seats No. 0	Axles 0							
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses								
Damaged items / restoration operations						SR		LA		VE		ME	D.M. S.C.	Costs of spare parts * (VAT excluded)
						Dif	Time	Dif	Time	Dif	Time	Time		
1	6VA807217F	Front bumper				S		S		S				
1	6VA8076119B9	Front bumper spoiler				S		S		S				
1	N10529501	Fog light bulb				L	S	S		S				
1	6VA949101	Fanalino lat. retrovisore est.				L	S	S		S				
1	5G0839167DGRU	Front door handle terminal				L	S	S		S				
1	6VE807421	Rear bumper				M		M		M				
1	6VA821105A	Front mudguard				L	L	L		L				
1	6VE809602D	Door sill				R	L	M		M				
1	Codice Ricambio	Riparazione fodera seduta sedile ant.				L								
1	Codice Ricambio	Cornice Griglia - PRM												
1	Codice Ricambio	Retro.re est. - PRM				L								
1	Codice Ricambio	Seconda chiave												
1	Codice Ricambio	Ricarica batteria												
1	Codice Ricambio	---												
1	Codice Ricambio	Note:												
1	Codice Ricambio	Quantificati i danni visibili e/o potenzialmente correlati												
1	Codice Ricambio	con quanto rilevabile												

New for old value (N)	Remarks Pneum. Kumho 185/65 R15. Vhl sporco. Mezzo non marciante per batt. scarica e disp. int. non testati. Note in corpo perizia
-----------------------	--