



Expertise

Protocol number: 46355501
Order No. / Reference: 26373355
Inspection date: 6 Jul 2026

Manufacturer: Volvo

Model: V90 T6 Recharge AWD Plus Bright

VIN: YV1PWH1V2P1192901



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volvo V90 T6 Recharge AWD Plus Bright	
Vehicle Identification number	YV1PWH1V2P1192901
Mileage (Read)	48,099 km
First registration	20 Feb 2023
Number of holders	1
Next periodical technical inspection	02/2028
(Report on hand)	
Power / Engine displacement	186 kw / 1,969 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufl / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Black Stone
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Light grey-White
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	222 Tag(e)
Last service on / at	02/2026 at 44,913 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ214861
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	9101 / BSB 00015		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,590 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100V	Winter tyres on Light alloy	Goodyear	7mm / 7mm
2)	245/45 R18 100V	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/40 R19 100W	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	255/40 R19 100W	Summer tyres on Light alloy	Michelin	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- ABS - Anti-lock Braking System
- Driver and passenger side airbags with two-stage deployment system
- Aluminum loading sill protector in the luggage compartment
- Dashboard and door trim in leather look with contrasting stitching
- Heated exterior mirrors and rear window (automatic)
- Outdoor temperature display
- Hill Start Assist (HSA)
- fog sensor
- On-board computer with vehicle control functions
- third brake light
- Chrome applications in the front bumper
- CleanZone air quality system
- Roof edge spoiler
- Digital services including Google Maps navigation system
- Driver Alert - Attention Warning
- Driver Awareness
- Rear parking assist with automatic braking intervention (rear)
- Electronic Stability Control (ESC)
- Advanced air purification system with fine dust filtration according to air quality standard PM2.5
- Automatic emergency braking
- Luggage compartment partition net
- Adaptive Cruise Control
- Transmission: 8-speed Geartronic
- Automatic tailgate (electric)
- rear window wiper
- Interior lighting
- Intelligent driver information system
- High-gloss black louvers in the center console
- Keyless Start
- Automatic air conditioning
- Rear headrests foldable, electrically
- Charging box under the cargo floor
- Cargo area roller blind (electric)
- LED headlights "Thor's Hammer"
- Steering wheel: Multifunction buttons on the steering wheel
- Emergency brake lights
- Ottopartiekelfilter (petrol particulate filter)
- Package: Seating comfort
- Electric parking brake
- Pollen filter
- Radio: Premium Sound audio system by Harman/Kardon
- Radio accessories: Smartphone integration Apple CarPlay
- Radio accessories: Two USB-C ports on the back of the center console
- Wheels: 19" alloy wheels, 8-spoke design, diamond cut/high-gloss black
- Safety Assistance
- Acoustic Vehicle Alerting System (AVAS)
- Airbag, passenger airbag can be deactivated
- Active safety belts with belt tensioners
- Ambient lighting
- Android infotainment system
- Electrically folding exterior mirrors
- Electrically adjustable exterior mirrors
- Exterior mirror caps in car color
- Attachment system for carrier bags in the luggage compartment
- LED turn signals integrated into the exterior mirrors
- Brake energy recuperation
- Chrome applications on the rear of the vehicle
- Chrome trim strip in the door sill area with Recharge lettering
- Aluminum roof rails (integrated)
- Digital Instrumentation 2nd Gen.
- Driver Assistance
- Inlays: Checkered aluminum inlay
- Aluminum door sill plates with Recharge lettering at the front and rear
- Electronic differential lock
- Electric windows front and rear
- Chrome window surround
- Front grille in waterfall design in chrome
- Luggage compartment lid release via remote control or from the driver's seat
- Front seat belt height adjustment
- Heated rear window
- Interior and exterior mirrors with automatic dimming function
- ISOFIX anchors for the outer rear seats
- Keyless Drive (electronic access system)
- Child safety lock for the rear doors, electric
- Headrests (5)
- Paint finish: Solid
- Charging cable Schuko/Type 2 (Mode 2), 7 m length, single-phase, 10 A
- Steering wheel adjustable for height and reach
- Illuminated makeup mirror for driver and front passenger
- One Pedal Drive
- Package: Parking Assistance
- Package: Winter Package
- Parking ticket holder
- Upholstery: Leather/leatherette comfort seats
- Radio accessory: Roof antenna (fin)
- Radio accessories: Subwoofer
- Rain sensor including automatic light function
- Run-off Road Protection
- Wheels: Tire pressure monitoring system (passive)
- Wheel accessories: Tire sealant
- Speed-sensitive power steering
- Safety steering column (adaptive)



- Safety braking system with disc brakes all around (internally ventilated)
- Sun blinds for the rear side windows (integrated)
- Start/Stop technology
- Fuel filler neck with misfuelling protection
- Premium textile floor mats, front and rear
- First aid kit and warning triangle
- Glazing: Acoustic glazing for the side windows
- Warning tone/indicator when seat belts are not fastened (for all seats)
- Central locking system with two remote controls and integrated emergency keys

- Seats: Rear seat backrests can be folded down in a 40/60 split or completely.
- Power outlet: 12-volt connection in the luggage compartment
- Trailer Stability Assist (TSA) - Preparation for trailer stability control
- Lashing eyes in the luggage compartment (foldable)
- Immobiliser
- WHIPS whiplash protection system

Extra equipment

- Surcharge Plus
- Panoramic glass sliding roof with lifting function (with integrated, continuously adjustable sunshade (electric))
- Parking camera with 360° surround view (including front, side and rear parking aid with automatic braking intervention (rear))
- Side and rear windows tinted (from the B-pillar back)

- Package: Light Package (Headlight cleaning system - Full LED headlights "Thor's Hammer" Active High Beam with extended high beam, dynamic cornering lights, intelligent high beam assistant with adaptive headlight range control and integrated LED daytime running lights)
- R471 Tailored Wool Sports Seats incl.

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Side panel - Scratched - Conditioning
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Door - rear left side	Door (Mit Kratzer) - dent(s) - Smart repair
4	Door - front left side	Door - dent(s) - Smart repair

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Front axle	Axle carrier - Corrosion - No deduction
3	Wheel / tyres	Alloy rim - front left side - Scratched - No deduction
4	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
5	Wheel / tyres	Alloy rim - rear left side - Scratched - No deduction
6	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Missing parts

Description

Equipment - charging cable (Mode 2)

Repainting

No. Repainting

1 Roof rail - right side, Side panel - rear right side, Door - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof rail - right side	201 µm	Side panel - rear right side	549 µm
Door - rear right side	142 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Für den montierten Radsatz wurde kein Nachweis erbracht.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.




Figure 37: Misc.



Damage 1: Side panel - rear right side: Side panel - Scratched - Conditioning



Damage 1: Side panel - rear right side: Side panel - Scratched - Conditioning



Damage 1: Side panel - rear right side: Side panel - Scratched - Conditioning



Damage 1: Side panel - rear right side: Side panel - Scratched - Conditioning



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 3: Door - rear left side: Door (Mit Kratzer) - dent(s) - Smart repair




Damage 3: Door - rear left side: Door (Mit Kratzer) - dent(s) - Smart repair



Damage 3: Door - rear left side: Door (Mit Kratzer) - dent(s) - Smart repair



Damage 4: Door - front left side: Door - dent(s) - Smart repair



Damage 4: Door - front left side: Door - dent(s) - Smart repair



Repainting 1: Roof rail - right side, Side panel - rear right side, Door - rear right side




Repainting 1: Roof rail - right side, Side panel - rear right side, Door - rear right side



Repainting 1: Roof rail - right side, Side panel - rear right side, Door - rear right side



Repainting 1: Roof rail - right side, Side panel - rear right side, Door - rear right side



Repainting 1: Roof rail - right side, Side panel - rear right side, Door - rear right side



Repainting 1: Roof rail - right side, Side panel - rear right side, Door - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: YV1PWH1V2P1192901

Hersteller / Modell: VOLVO VOLVO V90 T6 Recharge AWD Plus Bright

Datum	KM-Stand	Beschreibung
17.02.2026	44.913	AU; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges; Zündkerzen ern
17.02.2025	30.193	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
19.02.2024	14.627	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges