



MERCEDES C BREAK:

Vinnumber:	WDD2052011F922284	Versionname:	C 200 d Business Solution
First Registrationdate:	17/07/2019	Fiscalpower:	
Expertise Mileage:	171068	Power Kw:	118
Bodytype:		Body colour:	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3203
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

205/60/16/92 H				
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/60 R 16 92 H
Tyre size FR				205/60 R 16 92 H
Tyre size RL				205/60 R 16 92 H
Tyre size RR				205/60 R 16 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			2443,17
Interior, Stain, Forfeit			125,00



Bonnet, Dent(s), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Door RL, Dent(s) and scratch(es), Repair and paint (complete) 505,30



Door FL, Scratch(es), Spot repair 148,30



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Rear window, Scratch(es), Replace 574,85



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Wing RR, Dent(s) and scratch(es), Repair and paint (complete) 431,58



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03



Roof pillar R, Dent(s), Paintless dent repair

95,47

