



Toyota Corolla: N303BS

Vinnumber:	SB1Z93BE30E247205	Versionname:	Corolla 1.8 Hybrid 90kW Comfort Touring Sports CVT
First Registrationdate:	4/10/2021	Fiscalpower:	
Expertise Mileage:	108910	Power Kw:	90
Bodytype:		Body colour	Denim Blue metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Hybrid Petrol	Parking lot	693
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2	Hook
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 91 / H / Steel	3,9 mm	Bridgestone	Winter
	Right	195 / 65 / 15 / 91 / H / Steel	3,2 mm	Bridgestone	Winter
Rear	Left	195 / 65 / 15 / 91 / H / Steel	4,4 mm	Bridgestone	Winter
	Right	195 / 65 / 15 / 91 / H / Steel	4,2 mm	Bridgestone	Winter

Assistance equipment

Number of charging cables (rapid charge)	0
--	----------

Interior, Stain, Cleaning



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Bumper R, Crack, Repair and paint (complete)



Roof, Dent(s), Repair and paint (complete)



Kenteken	N303BS
Merk Model	Toyota Corolla 1.8 Hybrid 90kW Comfort Touring Sports CVT
Brandstofsoort	Benzine
Datum deel1	04-10-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
15-07-25	85.879	APK
15-07-25	85.879	Onderhoudsbeurt
15-07-25	85.879	Ruitenwischerblad(en) achterzijde
15-07-25	85.879	Ruitenwischerblad(en) voorzijde
15-07-25	85.879	Vervanging band
02-10-23	43.075	Onderhoudsbeurt
21-12-22	29.743	Onderhoudsbeurt
16-02-22	14.047	Onderhoudsbeurt