



Ford Kuga (UKL): 2APD244

Vinnumber:	WF0FXXWPMFMP08841	Versionname:	Kuga Trend 1.5 EcoBlue 120pk/cv 5p
First Registrationdate:	1/06/2021	Fiscalpower:	
Expertise Mileage:	120929	Power Kw:	88
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Maintenance book missing		
Type of GPS storage	HD		

Tyres

225/65/17/102 V				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/65 R 17 102 V
Tyre size FR				225/65 R 17 102 V
Tyre size RL				225/65 R 17 106 V
Tyre size RR				225/65 R 17 106 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Engine insulation, Missing, Check



Tailgate / Boot, Dent(s), Paintless dent repair





Kenteken	2APD244
Merk Model	Ford Kuga Trend 1.5 EcoBlue 120pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	6/1/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/24/25	105,681	120000 km	Uitvoeren
11/24/25	105,681	ad blue bijvullen	Bijvullen/-laden
11/24/25	105,681	brandstof hoofdfilter	Vervangen
11/24/25	105,681	luchtfilter	Vervangen
11/24/25	105,681	luchtfilter interieur	Vervangen
11/24/25	105,681	oliezeef	Vervangen
11/24/25	105,681	remblokken vooraan	Vervangen
11/24/25	105,681	remvloeistof	Vervangen
9/11/25	103,937	batterij	Vervangen
4/14/25	94,295	tech. keuring: nazicht/tijdens onderhou	Uitvoeren
11/5/24	84,081	80000 km	Uitvoeren
11/5/24	84,081	luchtfilter interieur	Vervangen
11/5/24	84,081	oliezeef	Vervangen
12/12/23	54,234	60000 km	Uitvoeren
12/12/23	54,234	batterij	Vervangen
12/12/23	54,234	brandstof hoofdfilter	Vervangen
12/12/23	54,234	luchtfilter	Vervangen
12/12/23	54,234	luchtfilter interieur	Vervangen
12/12/23	54,234	oliezeef	Vervangen
1/3/23	30,101	luchtfilter interieur	Vervangen
1/3/23	30,101	oliezeef	Vervangen
1/3/23	30,101	onderhoud 2e jaar	Uitvoeren