

INSPECTION REPORT

End of contract

GENERAL INFO

File	317083
License plate	2AQS741
Vehicle identification number	WBA31AC0305T89776
Dossier	2021 040 114
Make	BMW X1 sDrive 16d 85kW
Mileage	82155
First registration	15/06/2021
client availability date	02/07/2026
inspectionDate	13/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
18	Bumper Front / Spoiler / Replace	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	N
100	Door Rear Left // Smart Repair Small	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
154	Rear Bonnet // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
190	Door Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y

Damage Pictures




Door Rear Right // Smart Repair Small-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Smart Repair Small-scratch



Bumper Front // Painting-scratch




Front Left Door Interior Coating // Replace Completely-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent




Door Front Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent





Bumper Rear // Painting-bad repair



Interior // Repair 1-worn



Bumper Front / Spoiler / Replace-bad position



Bumper Front / Lower Cover Not Painted / Replace-bad position