DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VXKUKZKXZ PW129741	Registration date	21/12/2023	Exterior Color	Unknown
Brand	OPEL	Licence Plate	GL-A 7744E	Odometer	9 215 km
Model	MOKKA 100kW Elegance				

Inspection Details

Arrival Date	17/08/2026	Inspection ID	7120636	Inspection date	24/08/2026
Assign Date	17/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys SLC Essen



Generic equipment

Removable element

Spare wheel kit	✓
Toolkit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✓

Tyres

Goodyear 215/60/17 H All seasons
6.0 mm

Goodyear 215/60/17 H All seasons
6.0 mm

Goodyear 215/60/17 H All seasons
7.0 mm

Goodyear 215/60/17 H All seasons
7.0 mm

Exception / Damage

1



Part	Lower bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	105.00€
Damages	Scratched	Paint Time	0.70	Depreciation %	-
Severity	-	Paint cost	105.00€	Depreciation	-
Repair mode	Smart Repair	Flat Rate	105.00€	**Net Cost**	**105.00€**

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2



Part	Windscreen	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	-

3



Part	Bonnet	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	-

Summary Inspection

Gross Price	105.00€	Depreciation	-	Net Price	105.00€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	0.00€	0.00	0.00€	-	-	0.00€
Paintwork	150.00€	0.70	105.00€	-	-	105.00€
Paint preparation	150.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	0.00€	-	-	0.00€
Flat Rate	0.00€	-	-	0.00€