MACADAM









PEUGEOT E-208: GV-212-RH

Vinnumber:	**VR3UHZKWZR4046626**	Versionname:	**PEUGEOT E-208 Electrique 136ch Allure VP [5P] bva 1-136CH-4cv (bi-corps)**
First Registrationdate:	**12/03/2024**	Fiscalpower:	
Expertise Mileage:	**79331**	Power Kw:	**100**
Bodytype:	**Berline**	Body colour	**Blue**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Electric**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Seat cover lining	**Lining Semi-leather**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**195/55/16/91 H**			
	Fr.L.	**Michelin: 90%**	Fr.R.	**Michelin: 95%**
	Re.L.	**Michelin: 70%**	Re.R.	**Michelin: 80%**

Tyre profile depth FL	**2.1**
Tyre profile depth FR	**1.7**
Tyre profile depth RL	**3.6**
Tyre profile depth RR	**2.7**
Tyre size FL	**195/55 R 16 91 H**
Tyre size FR	**195/55 R 16 91 H**
Tyre size RL	**195/55 R 16 91 H**
Tyre size RR	**195/55 R 16 91 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Tyre FL, Out of tolerance, Replace




Tyre RL, Out of tolerance, Replace




Alloy rim RL bitone/polychrome, Scratch(es), Acceptable






Tyre RR, Out of tolerance, Replace




Alloy rim RR bitone/polychrome, Scratch(es), Acceptable







Tyre FR, Out of tolerance, Replace




Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)








Door FL, Scratch(es), Paint



Bumper F, Scratch(es), Paint










Wing RR, Dent(s), Acceptable





Door RR, Dent(s) and scratch(es), Repair and paint (complete)








Door FR, Scratch(es), Paint








Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Paint










Bumper moulding R, Deformed / Strained, Replace






Tailgate / Boot, Scratch(es), Paint








ALPHABET

Historique Maintenance

Immatriculation: **GV-212-RH** Date de 1ère immatriculation: **12/03/2024**

Modèle: **Peugeot E-208 Electrique 136ch Allure VP [5P] bva 1-136CH-4cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
22/10/2026	78.859	AUTO PASSION SERVICE	LAMPE RPLT
			REVISION
			FILTRE CLIM RPLT
			LIQUIDE DE FREIN
06/08/2025	30.001	AUTO PASSION SERVICE	REVISION
			FILTRE CLIM RPLT
			RECYCLAGE
21/02/2025	13.428	GARAGE DE TREMBLAY	REVISION