# APPRAISAL REPORT



## IDENTIFICATION VEHICLE

| | |
|---|---|
| **Driver name:** | ASSE I |
| **Make:** | SKODA |
| **Model / version:** | OCTAVIA COMBI |
| **Vin:** | TMBJP8NX9RY029466 |
| **Plate:** | 2EDP207 |
| **Mileage:** | 112218 |
| **SOH:** | |
| **First registration:** | 06/09/2023 |
| **Color:** | Brilliant si |

## ADDITIONAL INFORMATION


| | |
|---|---|
| **Category:** | |
| **Transmission:** | |
| **Interior color:** | |
| **Metallic paint:** | ? |
| **Type of lining:** | |
| **Board computer reset:** | ? |

## DOCUMENTS

| | |
|---|---|
| **Certificate of conformity:** | ✓ |
| **Registration certificate:** | ✓ |
| **Registration certificate 2:** | ✓ |
| **Insurance certificate:** | ? |
| **Maintenance book:** | |
| **Number of keys:** | 2 |
| **Original key:** | ✓ |


## PICTURES






















































## VIN INFORMATION

| | | |
|---|---|---|
| Radio | Radio avec système de navigation | 4 haut-parleurs |
| Bluetooth | Transmission séquentielle | 7 rapports |
| 5 portes | Break | Projecteurs antibrouillard |
| Lave-projecteurs | Feux arrière à LED | Buses de lave-vitre avant chauffantes |
| Essuie-lunette arrière | Equipement Style | Becquet arrière |
| Entourage de vitres chromé | Matière : alliage | Lettre repère (J) |
| Diamètre avant 16 | Diamètre arrière 16 | Largeur avant 7,0 |
| Largeur arrière 7,0 | Diamètre avant 16 | Diamètre arrière 16 |
| Hauteur avant 55 | Hauteur arrière 55 | Indice de vitesse avant V |
| Indice de vitesse arrière V | Largeur avant 205 | Largeur arrière 205 |
| Roue de secours tôle | Climatisation automatique 2 zones | Climatisation réfrigérant 1234YF |
| Accoudoir central avant | Accoudoir central arrière | Pare-soleil conducteur éclairé |
| Pare-soleil passager éclairé | Ordinateur de bord | Essence |
| 999 cm3 | 1.00 litre | 81 kw |
| 110 ch | Métallisée vernissée | Freins avant à disques |
| Freins arrière à disques | Frein à main électrique | Rétroviseur gauche jour/nuit automatique |
| Rétroviseur droit jour/nuit automatique | Rétroviseurs rabattables électriques | Rétroviseur intérieur jour/nuit automatique |
| Siège avant gauche chauffant | Sièges avant chauffants | Siège avant gauche réglable en hauteur |
| Sièges avant réglable en hauteur | 3ème appui-tête arrière | Fixations Isofix siège passager avant |
| Fixations Isofix aux places arrières | Garnitures tissu | Volant cuir |

| | | |
|---|---|---|
| Volant multifonction | Aide au stationnement avant | Aide au stationnement arrière |
| Caméra avant | Affichage lecture des panneaux de signalisation | Verrouillage centralisé à commande à distance |
| Carte mains libres | Appel de secours | Pare-brise athermique |
| Lunette arrière teintée foncée | Vitres portes arrière teintées foncées | Vitres de custode teintées foncées |
| Attelage avec boule rétractable électrique | Fixotoit aluminium | Airbag passager |
| Airbag passager désactivable | Airbag latéraux avant | Airbag de genoux |
| Airbag rideaux avant | Airbag rideaux arrière | Freinage d'urgence assistée autonome (urbain) |
| depuis 08.23 | éclairage périphérique Ambiente | sièges ar réglables électrique |
| capteur de luminosité/capteur de pluie | prise de courant 230 V | radio avec récepteur numérique |
| services Online | réservoir à charbon actif (EVAP) | transmission hybride M-HEV |
| airbag central pour sièges av | vide-poches dans le coffre | entretien à intervalle flexible (Long Life) QI6 |

## EQUIPMENT

| | | | |
|---|---|---|---|
| **Board computer:** | ? | **Central locking:** | ? |
| **Compressor:** | × | **Cruise control:** | ? |
| **Gps:** | ? | **Power steering:** | ? |
| **Rear parking sensor:** | ? | **Repair kit:** | × |
| **Front seats heated:** | ? | **Steering wheel:** | ? |
| **Electric windows:** | ? | **Climate control type:** | |
| **Headlighting type:** | | **Tow bar type:** | |
| **Charging cables:** | 0 | **Fast charging cables:** | 0 |

## TIRES

| Position | Depth | Brand | Dimensions | Type | Rims | Runflat |
|---|---|---|---|---|---|---|
| Front left | 5 mm | Kumho | | Summer | Aluminium | × |
| Front right | 5 mm | Kumho | | Summer | Aluminium | × |
| Rear left | 5 mm | Kumho | | Summer | Aluminium | × |
| Rear right | 5 mm | Kumho | | Summer | Aluminium | × |

## DAMAGES SUMMARY

**NOT ACCEPTABLE / TO BE INVOICED**

| # | Location | Damage type |
|---|---|---|
| 1 | Boot lid covering R | Dirty |
| 2 | Seat cover FL | Dirty |
| 3 | Alloy rim FL | Dent(s) and scratch(es) |
| 4 | Bonnet | Dent(s) |
| 5 | Bumper F | Dent(s) and scratch(es) |
| 6 | Door RL | Dent(s) and scratch(es) |
| 7 | Wing RL | Dent(s) |
| 8 | Tailgate / Boot | Dent(s) and scratch(es) |
| 9 | Bumper R | Dent(s) and scratch(es) |
| 10 | Door RR | Dent(s) |
| 11 | Door FR | Bad repair |

**Total: 11**

**ACCEPTABLE / NOT TO BE INVOICED**

| # | Location | Damage type | Renta® | Repaired | Already invoiced |
|---|---|---|---|---|---|
| 1 | Bodywork | Dent(s) and scratch(es) | ✓ | × | × |

**Total: 1**

## DAMAGES DETAILS

### 1 - Boot lid covering R - Dirty






### 2 - Seat cover FL - Dirty






### 3 - Alloy rim FL - Dent(s) and scratch(es)





### 4 - Bonnet - Dent(s)





### 5 - Bumper F - Dent(s) and scratch(es)







### 6 - Door RL - Dent(s) and scratch(es)





### 7 - Wing RL - Dent(s)




## 8 - Tailgate / Boot - Dent(s) and scratch(es)







## 9 - Bumper R - Dent(s) and scratch(es)






## 10 - Door RR - Dent(s)





## 11 - Door FR - Bad repair





## 1 - Bodywork - Dent(s) and scratch(es) - Renta®






## SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

**Expert**

13/10/2026 08:44

PH