MACADAM








TOYOTA C-HR: 4235-MGW

Vinnumber:	**NMTK53BX20R107326**	Versionname:	**2.0 180H Advance berlina con portón 135kW 5P automática**
First Registrationdate:	**18/05/2023**	Fiscalpower:	
Expertise Mileage:	**174170**	Power Kw:	
Bodytype:	**MPV**	Body colour	**Dark Red**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Hybrid**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**No**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**2**	Luggage cover	
GPS big screen color		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**225/50/18/99 W**			
	Fr.L.	**Nexen: 5 mm**	Fr.R.	**Nexen: 5 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**225/50 R 18 99 W**
Tyre size FR	**225/50 R 18 99 W**
Tyre size RL	**225/50 R 18 99 W**
Tyre size RR	**225/50 R 18 99 W**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**1957072**
Tyre make FR	**1957072**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**No**	Compressor	**No**

Door panel RR, Scratch(es), Replace




MOT certificate, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)




Door RL, Dent(s) and scratch(es), Repair and paint (complete)




Door FL, Scratch(es), Repair and paint (complete)




Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Outer sill L, Dent(s), Repair and paint (complete)




Fender moulding FR, Scratch(es), Repair and paint (complete)




Wing FR, Dent(s) and scratch(es), Repair and paint (complete)




Door FR, Scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)




Fender moulding RR, Scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Repair and paint (complete)




Tyre repair kit, Missing, Repair/replace (lump sum)




Bumper R, Scratch(es), Repair and paint (complete)





Spoiler R, Scratch(es), Repair and paint (complete)




Tyres, No damage, Check










ALPHABET

Datos del vehículo

Marca	TOYOTA	Matrícula	4235-MGW
Modelo	C-HR	VIN	NMTK53BX20R107326
Versión	2.0 180H Advance berlina con portón 135kW 5P automática		

Histórico

Fecha	Descripción	Kilómetros	Taller
31/10/2023	Rev. 15.000 kms	16057	BREOGAN MOTOR S.L.
31/01/2024	Rev. 30.000 kms	30146	ASTURHIBRIDO S.L.
27/03/2024	Luna parabrisas	36152	RALARSA HOLDING S.L.
03/06/2024	Rev. 45.000 kms	45343	BREOGAN MOTOR S.L.
11/06/2024	Sustitución	46328	MULTIMARCA JAEMI S.C.G.
30/09/2024	Revisión 4 años	61530	HYBRID CAR S.A.
15/11/2024	Sustitución	72699	NEUMATICOS SOLEDAD S.L.
29/11/2024	Revisión 5 años	76209	HYBRID CAR S.A.
10/12/2024	Luna parabrisas	77127	RALARSA HOLDING S.L.
19/03/2025	Rev. 90.000 kms	91867	HYBRID CAR S.A.
20/06/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter, Filtro aceite - OPTIFIT - Economic, Líquido lavaparabrisas, Serv inspección 105000 KM, Sustituir Líquido lavaparabrisas, Tasa de gestión de aceites usados	106591	HYBRID CAR S.A.
19/09/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter, Escobilla dr limpiaparabrisas - OPTIFIT - Economic, Escobilla iz limpiaparabrisas - OPTIFIT - Economic, Escobilla limpialuna	122365	HYBRID CAR S.A.

Fecha	Descripción	Kilómetros	Taller
	tr, Filtro aceite - OPTIFIT - Economic, Filtro aire, Filtro antipolen - OPTIFIT - Economic, Filtro ventilador acumulador carga, Líquido frenos - DOT4 SAE - Nueva, Líquido lavaparabrisas, Serv inspección 120000 KM, Sustituir Escobilla limpialuna tr, Sustituir Escobillas limpiaparabrisas, Sustituir Líquido lavaparabrisas, Tasa de gestión de aceites usados		
05/12/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter - AJUSA - Rec.Plat. EuroTaller, Filtro aceite - PURFLUX - Rec.Plat. EuroTaller, Serv inspección 135000 KM, Tasa de gestión de aceites usados	137852	Eduardo Javier Martin Bruña
15/06/2026	Ecotasa - BT, NEXEN / 14283NX - NBLUE4S - 225/50 R18 99W, Sustitucion y kit de montaje	162817	JULIO GARCIA HERRERO S.L.