



Expertise

Protocol number: 46637404
Order No. / Reference: 26681265
Inspection date: 22 Jul 2026

Manufacturer: Opel

Model: Grandland X 1.5 D Start/Stop Automatik Business Edition

VIN: W0VZCYHZ9M6820974



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Grandland X 1.5 D Start/Stop Automatik Business Edition	
Vehicle Identification number	W0VZCYHZ9M6820974
Mileage (Read)	173,461 km
First registration	16 Apr 2021
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Mondstein Grau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	20,380 km
Last service on / at	04/2026 at 163,842 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA196540
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AHG 00156		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,000 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99V	Summer tyres on Light alloy	Continental	3mm / 3mm
2)	215/65 R17 99V	Summer tyres on Light alloy	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 103H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	215/65 R17 103H	Winter tyres on Light alloy	Continental	9mm / 9mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 folding ignition keys
- Storage compartments
- Airbag: Chest-pelvis-side airbags, driver and front passenger
- Electrically folding exterior mirrors
- Hill Start Assist
- Braking system: Regenerative
- Decorative trim, Frosted Silver
- Tachometer
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Cruise control with intelligent speed limiter
- rear window wiper
- Instrument panels in black, with rings in high-gloss black, 3.5" color driver information display
- Rear headrests (3), height adjustable
- Paint finish: Metallic Ruby Red
- Leather steering wheel including remote control
- Illuminated makeup mirrors in both sun visors
- Fog light
- Parkpilot, front and rear parking aid
- Quickheat heating system
- Radio accessories: Digital radio reception DAB+
- Wheels: Light alloy 7 J x 17 with 5 double spokes
- Reversing camera and front and rear parking sensors
- Speed-sensitive power steering
- Seats: 5 seats
- Lane Assist
- Start/Stop System
- Phone: Wireless Charging
- Lashing eyes in the luggage compartment (4)
- Immobiliser
- Tinted heat-insulating glazing
- Low beam automatically
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- On-board computer
- Roof design line in black
- Diesel particulate filter with SCR and oxidation catalyst
- Electric parking brake
- Electronic Stability Program Plus (ESP Plus)
- Luggage compartment cover
- Transmission: 8-speed automatic
- Interior lighting, front and rear, with reading light at the front.
- Child safety lock in the rear doors, manual
- Air conditioner with particle and odor filter
- Front headrests, height adjustable
- LED headlights
- Steering wheel, height and reach adjustable
- Center armrest, sliding, front, including storage compartment and cup holder
- Upholstery: Fabric/Premium leather look
- Radio: R4.0 IntelliLink
- Tire pressure warning
- Wheels: Tire repair kit
- Service interval indicator
- Seat belts
- Seats: Ergonomic active seat with AGR seal of approval, driver
- 12-volt power outlet
- Traffic sign recognition
- Pre-wiring for ISOFIX child seat mounting system, including top tether attachment points, rear outer
- Central locking with remote control and interior switches



Extra equipment

- Forward Collision Warning with Automatic Emergency Braking and Pedestrian Detection (monitors the distance (close, medium, far) to the vehicle ahead; if the vehicle approaches a vehicle or pedestrian too quickly, a warning tone sounds and a message appears in the driver information display. If a collision is imminent, the braking system is prepared and, if necessary, emergency braking is initiated to minimize the consequences of a potential collision. - Lane Keeping Assist: warns if the vehicle unintentionally leaves its lane - Driver Fatigue Detection)
- Paint finish: Metallic
- Park & Go Premium (360-degree camera - Automatic parking assistant, including front and rear parking sensors - Electrically folding exterior mirrors with ambient lighting - Blind spot warning in both exterior mirrors (active between 12 km/h and 140 km/h) - Navi 5.0 IntelliLink: 8" color touchscreen display and voice control for audio, telephone and navigation, Bluetooth audio streaming, hands-free system, smartphone integration via Apple CarPlay™ and Android Auto, 2 USB ports, dual tuner, 6 speakers)
- Automatic speed assistant with stop function (Automatic speed assistant maintains the set speed and the selected distance (close, medium, far) to the vehicle in front by means of automatic braking intervention or automatic acceleration (activation from 30 km/h to 180 km/h))
- Detachable trailer hitch (trailer stability program)
- Dual-zone automatic climate control (with separate temperature control for driver and front passenger - recirculation mode, manual - automatic air distribution - sun position sensor - particle and odor filter)
- Heated ThermoTec windshield
- Interior features (rear seats split and foldable in a 40:60 ratio - rear center armrest with pass-through from the luggage compartment - luggage compartment floor, adjustable to two heights - luggage compartment lighting)
- Seats: Seat heating (multi-stage, driver and front passenger; heated leather steering wheel)
- winter tires

Retrofitted equipment

- winter tires

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear right side	Door - dent(s) - Smooth repair work
2	Bonnet	Bonnet (schleifen und polieren) - Soiled - Smart repair
3	Front bumper	Front bumper (unpainted) - Scratched - Replace
4	Side panel - rear right side	Sill - Scratch(es) - Smart repair
5	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
6	Trim / covers	Door trim - rear left side - Scratch(es) - Smart repair
7	Mudguard - left side	Mudguard - left side - Scratch(es) - Smart repair
8	Seat - front	Seat cover - left side - Porous / cracked - Loss in value
9	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value
10	Side panel - rear left side	Wheel well extension - Scratch(es) - Replace
11	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
12	Bonnet	Insulation lining - Damage caused by marten / rodent - Replace
13	Rear bumper	Rear bumper - Scratch(es) - Paint



Wear and tear

No.	Component group	Description
1	2nd wheel set	1 alloy rim - Scratch(es) - No deduction
2	Engine	Engine cover - Damage caused by marten / rodent - No deduction
3	Door - front right side	Door - Scratch(es) - No deduction
4	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
5	Trim / covers	Boot sill cover - Scratch(es) - No deduction
6	Steering system	Steering wheel - Abrasion - No deduction
7	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No. Repainting

- 1 Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
- 2 Door - rear left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear left side	193 µm	Door - rear left side	243 µm
-----------------------------	--------	-----------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist Bestandteil der Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Damage 1: Door - rear right side: Door - dent(s) - Smooth repair work




Damage 1: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 2: Bonnet: Bonnet (schleifen und polieren) - Soiled - Smart repair



Damage 2: Bonnet: Bonnet (schleifen und polieren) - Soiled - Smart repair




Damage 3: Front bumper: Front bumper (unpainted) - Scratched - Replace




Damage 3: Front bumper: Front bumper (unpainted) - Scratched - Replace



Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 6: Trim / covers: Door trim - rear left side - Scratch(es) - Smart repair



Damage 6: Trim / covers: Door trim - rear left side - Scratch(es) - Smart repair




Damage 7: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 7: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair




Damage 8: Seat - front: Seat cover - left side - Porous / cracked - Loss in value




Damage 8: Seat - front: Seat cover - left side - Porous / cracked - Loss in value




Damage 9: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 9: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value




Damage 10: Side panel - rear left side: Wheel well extension - Scratch(es) - Replace



Damage 10: Side panel - rear left side: Wheel well extension - Scratch(es) - Replace



Damage 11: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair




Damage 11: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 11: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 12: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 12: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Wear and tear 2: Engine: Engine cover - Damage caused by marten / rodent - No deduction



Wear and tear 2: Engine: Engine cover - Damage caused by marten / rodent - No deduction



Repainting 1: Side panel - rear left side



Repainting 2: Door - rear left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZCYHZ9M6820974
Hersteller / Modell: OPEL OPEL Grandland X 1.5 D Start/Stop Automatik Business Edition

Datum	KM-Stand	Beschreibung
27.04.2026	163.842	AU
14.04.2026	163.842	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Regelwartungsdienst
03.11.2025	147.746	Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne
24.09.2025	145.743	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
26.02.2025	125.745	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
25.02.2025	122.985	Getriebeöl ern/prüfen; Reparatur Sonstiges; Systemtest/Eigendiagnose
15.01.2025	109.106	Systemtest/Eigendiagnose
19.08.2024	109.106	Keilrippenriemen; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Regelwartungsdienst
09.04.2024	99.046	AU
18.01.2024	89.807	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges
10.10.2023	75.818	Reparatur Sonstiges
17.03.2023	62.928	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
29.07.2022	22.029	Motoröl b. Wartung; Motoröl b. Wartung; Ölfilter ern; Ölfilter ern; Regelwartungsdienst; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges