

Vehicle details

VIN	KMHM241A1 PA057091	Brand	HYUNDAI	Maintenance date	-
Licence Plate		Model	IONIQ 6 77,4kWh Style 4d Onze Deal	Maintenance mileage	-
Registration date	02/01/2024	Year	2024	Exterior Color	Grey Metallic
Odometer	181 316 km	Engine size	-	Interior Color	Grey
Fuel	Electric	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	20/07/2026	Inspection loc.			
					
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 225/55/18 Summer 4.0 mm



Michelin 225/55/18 Summer 4.0 mm



Goodyear 225/55/18 Summer 5.0 mm



Goodyear 225/55/18 Summer 4.0 mm

Exterior

1



Part	Step plate
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	For info

3



Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

5



Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



Part	Door
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

7



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Tailgate / Boot door
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

9



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

10



Part	Door
Position	Back right
Damages	Improper repair
Severity	-
Repair mode	Repair

11



Part	Door
Position	Front right
Damages	Improper repair
Severity	-
Repair mode	Repair

12



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

13



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

14



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

15



Part

Position

Damages

Severity

Repair mode

Wing

Front right

Improper repair

-

Repair

Interior damage

2



Part

Position

Damages

Severity

Repair mode

Interior cleaning

Front

Stained/dirty

-

Cleaning

4



Part

Position

Damages

Severity

Repair mode

Boot carpet

-

Scratched

-

For info