



Audi A3:

Vinnumber:	WAUZZZGY6NA042121	Versionname:	
First Registrationdate:	15/02/2022	Fiscalpower:	
Expertise Mileage:	70801	Power Kw:	81
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2223
Fueltype:	Hybrid Petrol		
Maintenance	NOT OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

	225/55/16/92 H			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 16 92 H
Tyre size FR				225/55 R 16 92 H
Tyre size RL				225/55 R 16 92 H
Tyre size RR				225/55 R 16 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	429,61
Service, Maintenance, Check	0,00



Bumper F, Scratch(es), Repair and paint (complete)	296,58
--	--------



Wing RL, Dent(s), Acceptable	0,00
------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Bumper R, Deformed / Strained, Replace and paint	0,00
--	------



Bumper moulding R, Missing, Replace	0,00
-------------------------------------	------



Reflector, Crack, Replace	0,00
---------------------------	------



Tailgate / Boot, Scratch(es), Repair and paint (complete)	0,00
---	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Wing FR, Deformed / Strained, Replace and paint	0,00
---	------



Wheel arch cover FR, Deformed / Strained, Replace	0,00
---	------



Door FR, Dent(s), Repair and paint (complete)	0,00
---	------



Outer sill R, Deformed / Strained, Replace and paint	0,00
--	------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------

