



2-FSG-887


2-FSG-887 · FR 1,0L TSI 110HP DSG KJ75RZ E05 · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FSG-887	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ9RR186331
Model	Arona	Cylinder Capacity	999 ^{cm³}
Model Versions	FR 1,0L TSI 110HP DSG KJ75RZ E05	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	02-08-2024
Color	Black	Odometer	84.254 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	85	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate



Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Lassa	205 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Rear Left	4 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	4 ^{mm}	Lassa	205 ^{mm}	55 ^{mm}	17 ^{inch}	All Season
Rear Right	4 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	None					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Overfender

Scratch(es)

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Left Front

Damaged

Rim repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Windscreen - Front

Broken

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

spoiler FB

Scratch(es)

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type


Acceptable

Bumper - Front

Scratch(es)

Panelbeating & Spray

No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Front Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Right	Small scratch(es)	Polish	No




Damage Part
Bumper - Rear

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Tailgate

Damage Type
Dent(s)

Repair Type
Panelbeating & Spray

Acceptable
No



Damage Part
Interior

Damage Type
Worn

Notes
Vloerbedekking

Repair Type
Cloth Repair
Acceptable
No




Damage Part
Skirt - Right

Damage Type
Small scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Interior

Damage Type
Stains & dirt

Repair Type
Cleaning

Acceptable
No