



PEUGEOT 308: 6271-LSV

Vinnumber:	VF3LCYHZJMS177359	Versionname:	SW Style BlueHdi 130 S&S familiar 96kW 5P manual
First Registrationdate:	15/09/2021	Fiscalpower:	
Expertise Mileage:	104474	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Central consol F
Number keys remote	1	Luggage cover
GPS big screen color		Rear parking sensors
Windows electric F		Roof bar alu
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

205/55/16/91 H				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes
------------	------------

Boot lid covering R, Scratch(es), Repair/replace (lump sum)



Steering wheel, Scratch(es), Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing FL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror R, complete, Scratch(es), Repair and paint (complete)




Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering

