

Jobnr Fleet Lease Driver Location Date Date Hour	Make DACIA Model NEW SANDERO Type Licenseplate Chassisnr UU1DJF00474846425 Color Bruin First Registration 08-05-2025 Mileage 26055 VP/VU VP Fuel petrol Fuel Level 8/8 Total Keys 1 Seats MVP 5
---	--

Check COC No Registration doc No Insurance doc No Manual Yes Service book No Fire extinguisher Yes Rear Shelf Yes	Safety Kit Yes Triangle Yes GPS Yes Fuel Card No Alarm Yes Service Needed No
--	---

Remarks

Signatures

This damage review contains the exterior and interior damages of the vehicle. The repair costs of the exterior and interior damage of the vehicle will be added afterwards. These repair costs will be part of the damage review. This norm is developed by Renta, the Belgian federation of rental companies.

This norm can be consulted on their website www.renta.be. The Rentanorm is generally accepted by fleetowners and drivers as a guidance but is not binding in any way. This damage review does not count as an insurance/damage calculation as meant in the application of the law involved.


This signature means that I agree with the registered damages on my company car. I will receive a report of the registered damages by mail. This report contains no calculated damage amounts. Later the damage amounts will be calculated and added to this report, and then sent to the fleetmanager. Signing this report does not implicate my automatic acceptance of the damage amounts. A compensation on the damage amounts will be charged in accordance with the car policy of your company.

Damage advisor

Driver



exterior	19 DoorRR	DOOR RR	NA	scratch + dent	Repair + paint
exterior	16 Roof	ROOF-PILLAR R	NA	bad repair	SR - Spot repair
exterior	16 Roof	ROOF	NA	scratch	SR - Polish
exterior	10 DoorRL	MOULDING RL	NA	worn	Replace
exterior	23 WingFR	WING FR	NA	scratch + dent	SR - PDR
exterior	30 Extra	STICKERS	NA	Remainder stickers	Remove stickers
interior	26 CoverRoof	REPAIR 1	NA	scratch	SR - Structure
interior	3 Console	CONSOLE	NA	scratch	SR - Structure
exterior	29 Cleaning	CLEANING	NA	stain	Cleaning
exterior	13 BumperR	BUMPER REAR	A	scratch	Paint
exterior	3 Bonnet	BONNET	A	dent	SR - PDR
interior	18 CarpetTrunk	REAR COVER	A	scratch	Paint

General Pictures





Damage Appraisal



exterior	19 DoorRR	DOOR RR	NA scratch + dent	Repair + paint
----------	-----------	---------	-------------------	----------------



exterior	16 Roof	ROOF-PILLAR R	NA bad repair	SR - Spot repair
----------	---------	---------------	---------------	------------------



exterior	16 Roof	ROOF	NA scratch	SR - Polish
----------	---------	------	------------	-------------




exterior	10 DoorRL	MOULDING RL	NA worn	Replace
----------	-----------	-------------	---------	---------



exterior	23 WingFR	WING FR	NA scratch + dent	SR - PDR
----------	-----------	---------	-------------------	----------



exterior	30 Extra	STICKERS	NA Remainder stickers	Remove stickers
----------	----------	----------	-----------------------	-----------------



interior	26 CoverRoof	REPAIR 1	NA scratch	SR - Structure
----------	--------------	----------	------------	----------------



interior	3 Console	CONSOLE	NA scratch	SR - Structure
----------	-----------	---------	------------	----------------



exterior	29 Cleaning	CLEANING	NA stain	Cleaning
----------	-------------	----------	----------	----------



exterior	13 BumperR	BUMPER REAR	A scratch	Paint
----------	------------	-------------	-----------	-------



exterior	3 Bonnet	BONNET	A dent	SR - PDR
----------	----------	--------	--------	----------



interior	18 CarpetTrunk	REAR COVER	A scratch	Paint
----------	----------------	------------	-----------	-------



Vehicle Condition	Interior: clean
	Exterior: clean

Tyres			
Type	Summer	Flat/RSC	No
Spare Tyre	Yes	Repair Kit	No
Front Left			
Profile	3	Side Damage	No
Front Right			
Profile	3	Side Damage	No
Rear Left			
Profile	4	Side Damage	No
Rear Right			
Profile	4	Side Damage	No