


Vehicle details

VIN	WAUZZZGE9 NB044526	Brand	AUDI	Maintenance date	-
		Model	E-tron 55 quattro edition 5d	Maintenance mileage	-
Registration date	20/07/2022	Year	2022	Exterior Color	Mythoszwart metallic
Odometer	163 629 km	Engine size	-	Interior Color	Unknown
Fuel	-	Body Type	-	Next technical inspection	-
Seats	-	Transmission	-	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date 22/07/2026



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Central locking	✓
Electric windows	✓
4x4	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Load cover	✓
Vehicle charger	✓
Wireless charger	✗

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 255/50/20 All seasons
5.0 mm

Continental 255/50/20 All seasons
5.0 mm

Continental 255/50/20 All seasons
7.0 mm

Continental 255/50/20 All seasons
5.0 mm

Exterior

2



Part	Wing
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair



3



Part	Wing moulding
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair



6



Part	Tailgate / Boot door
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair



7



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair



8



Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair



9



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair




10



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair



11



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info



12



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair



Interior damage

4



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning



5



Part

Interior cleaning

Position

Back

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

Others

1



Part

Wireless charger

Position

-

Damages

Missing

Severity

-

Repair mode

For info