



Expertise

Protocol number: 46558011
Order No. / Reference: 26534766
Inspection date: 16 Jul 2026

Manufacturer: Opel

Model: Zafira Life 2.0 D M Aut. Elegance

VIN: VXEEVHZ7NZ018080



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Zafira Life 2.0 D M Aut. Elegance	
Vehicle Identification number	VXEEVHZ7NZ018080
Mileage (Read)	58,735 km
First registration	14 Apr 2022
Number of holders	1
Next periodical technical inspection	04/2027
Power / Engine displacement	130 kw / 1,997 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade Weiß
Doors / Seats	5 / 7
Upholstery type	Leather
Colour of upholstery	Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	44,280 km
Last service on / at	11/2025 at 52,957 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ644494
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	3003 / BBA 00337		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,830 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/55 R17 101Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Winter tyres on Light alloy	Dunlop	7mm / 7mm
2)	225/55 R17 101V	Winter tyres on Light alloy	Dunlop	8mm / 8mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Low beam automatically
- Airbag for driver and passenger side
- Airbag: Curtain airbags, in the 2nd and 3rd rows of seats
- Automatic activation of the hazard warning lights
- Exterior mirror housings in black
- On-board computer
- Headliner with 3 reading lights and ambient lighting
- Tachometer
- Window: Window, driver's side in the 2nd row of seats, fixed
- Luggage compartment cover
- Electric handbrake
- Glazed tailgate, with rear window wiper and heater
- Interior mirror, automatically dimming
- Child safety lock, electric
- Automatic climate control: Dual-zone automatic climate control
- Headlight range adjustment, manual
- Navigation system: Multimedia Navi Pro with 7" color touchscreen display, voice control for audio, telephone, navigation
- Package: Driver Assistance Package 2
- 180° panoramic reversing camera
- Parkpilot, front and rear
- Radio: Digital radio reception DAB+
- Rain sensor
- Tire pressure warning
- Sliding door trim with cover, in vehicle color
- Side impact protection
- Power steering
- Safety steering column, height and length adjustable
- Heated seats for driver and front passenger
- Sun visors driver and passenger side
- 12-volt power outlet in the second row of seats
- Power outlet: 220/230V, in the second row of seats under the passenger seat
- Exterior door handles, in chrome
- Immobiliser
- Central locking with remote control
- Storage compartments
- Airbag: Head airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Exterior mirrors, electrically adjustable, heated and folding
- Hill Start Assist
- Third brake light
- Diesel particulate filter
- Electronic Stability Program (ESP Plus)
- Electric front windows
- Floor mats in all rows of seats
- Transmission: 8-speed automatic transmission
- Head-Up Display
- Interior lighting
- Interior mirror, additional, for interior monitoring
- Air conditioning: Auxiliary air conditioning, rear
- Paint finish: Solid
- Steering wheel: Multifunction leather steering wheel, flattened at the bottom
- Fog light
- Rear fog lights with reversing lights
- Package: Driver Assistance Package 1
- Panoramic glass roof with 2 separate windows, manually retractable
- Quickheat rapid heating system
- Radio accessories: Sound system
- Tire repair kit
- Wheels: Alloy wheels in bicolor, 7J x 17
- Keyless locking and starting system Keyless Open & Start
- Side protection strips in vehicle color
- Seat belts: Three-point seat belts in all seats
- Seats: 8 leather seats, Claudia Schwarz
- Solar Protect thermal insulation glazing
- Sunshades in the 2nd row of seats
- 12V socket
- Traction Control (TC) Plus
- Door: Electric sliding door, driver and passenger side
- Illuminated door sill trim
- Xenon headlights with LED daytime running lights
- Ignition keys (2), both foldable



Extra equipment

- Folding table on rail system (movable between 2nd and 3rd row of seats, removable)
- Seats: 7 leather seats, Claudia Schwarz (Comfort driver's seat: 6-way electrically adjustable, with lumbar support, armrest, massage function and seat heating; Comfort passenger seat: 4-way electrically adjustable, with lumbar support, armrest, massage function and seat heating; Two individual seats on rails in the 2nd row with armrests, swivel, foldable and removable and ISOFIX preparation; Bench seat in the 3rd row, foldable in a 1/3 to 2/3 ratio and ISOFIX preparation; Rail system for 2nd and 3rd rows; Height-adjustable headrests)
- Anti-theft alarm system
- Detachable trailer hitch
- IntelliGrip (Adaptive traction system with 5 selectable modes: - ESP off - ESP standard - Snow mode - Mud mode - Sand mode)
- Luggage compartment partition net (vertical behind the last row of seats)
- Package: Design Package Black Edition (Exterior mirror housings in high-gloss black - Side protection strip in high-gloss black)
- Webasto auxiliary heater (programmable with remote control)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Gearbox	Gearbox - Leaking - Perform diagnosis
2	Body	Body - Glued / labelled - De-glue / neutralise
3	Engine	Engine cover - Damaged - Replace

Wear and tear

No.	Component group	Description
1	Seat - front	Seat cover - left side - Abrasion - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Heating system - Remote control auxiliary heating

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Gearbox: Gearbox - Leaking - Perform diagnosis



Damage 1: Gearbox: Gearbox - Leaking - Perform diagnosis



Damage 2: Body: Body - Glued / labelled - De-glue / neutralise




Damage 2: Body: Body - Glued / labelled - De-glue / neutralise



Damage 3: Engine: Engine cover - Damaged - Replace



Wear and tear 1: Seat - front: Seat cover - left side - Abrasion - No deduction



Wear and tear 1: Seat - front: Seat cover - left side - Abrasion - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VXEVEEHZ7NZ018080

Hersteller / Modell: OPEL OPEL Zafira Life 2.0 D M Aut. Elegance

Datum	KM-Stand	Beschreibung
24.11.2025	52.957	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
09.09.2025	28.161	Batterie ern
09.04.2025	51.599	HU + AU
15.03.2024	34.200	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Regelwartungsdienst
02.02.2024	29.287	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges