



Peugeot 208: T778BV

| | | | |
|-------------------------|--------------------------|-------------------------|---|
| Vinnnumber: | VR3UHZKXZPT562396 | Versionname: | e-208 50kWh 100kW Allure Pack automaat |
| First Registrationdate: | 30/05/2023 | Fiscalpower: | |
| Expertise Mileage: | 61581 | Power Kw: | 100 |
| Bodytype: | | Body colour: | Rouge Elixir metaallak |
| Gearbox: | Automatic | Paint type: | Metallic |
| Transmission: | | Type of rims (mounted): | Aluminium |
| Fueltype: | Electric | Parking lot: | 708 |
| Number of seats: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Maintenance needed: | No | | |

Options

| | | |
|-----------------------|----------|----------------------|
| Number of keys total | 2 | Lining semi-leather |
| Autom climate control | | Rear parking sensors |
| Radio multimedia | | Rear view camera |

Tyres

| Location | Position | Measures | Depth | Make | Type |
|----------|----------|------------------------------------|--------|-------------|--------|
| Front | Left | 195 / 55 / 16 / 91 / H / Aluminium | 6,0 mm | Continental | Winter |
| | Right | 195 / 55 / 16 / 91 / H / Aluminium | 7,8 mm | Continental | Winter |
| Rear | Left | 195 / 55 / 16 / 91 / V / Aluminium | 5,5 mm | Michelin | Winter |
| | Right | 195 / 55 / 16 / 91 / V / Aluminium | 6,5 mm | Michelin | Winter |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (rapid charge) | 1 |
|--|----------|

Interior, Stain, Cleaning



Wheel arch cover RL, Broken, Replace



Door RL, Bad repair, Repair and paint (complete)




Door FL, Scratch(es), Repair and paint (complete)



Bonnet, Hail damage, Paintless dent repair (hail)



Windscreen, Stone chip(s), Windscreen repair



Door RR, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)



Roof, Hail damage, Paintless dent repair (hail)



| | |
|-----------------------|--|
| Kenteken | T778BV |
| Merk Model | Peugeot e-208 50kWh 100kW Allure Pack automaat |
| Brandstofsoort | Elektrisch |
| Datum deel1 | 30-05-23 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|-----------------|----------------|-----------------------------------|
| 30-06-26 | 61.517 | Onderhoudsbeurt |
| 30-06-26 | 61.517 | Vervanging band |
| 29-06-26 | 61.447 | Ruitenwischerblad(en) achterzijde |
| 29-06-26 | 61.447 | Ruitenwischerblad(en) voorzijde |
| 04-12-24 | 25.040 | Onderhoudsbeurt |