APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	SKODA
Model / version:	KAMIQ
Vin:	TMBGP6NW6P3112885
Plate:	2DNA940
Mileage:	92775
First registration:	02/05/2023
Color:	Brilliant Si

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES



















































VIN INFORMATION

Radio	Radio avec système de navigation	8 haut-parleurs
Boîte manuelle	5 rapports	Pommeau de levier de vitesses cuir
Projecteurs à allumage automatique	Feux arrière à LED	Buses de lave-vitre avant chauffantes
Equipement Confort	Entourage de vitres chromé	Poignées de portes ton caisse
Matière : alliage	Lettre repère (J)	Diamètre avant 17
Diamètre arrière 17	Largeur avant 6,5	Largeur arrière 6,5
Diamètre avant 17	Diamètre arrière 17	Hauteur avant 55
Hauteur arrière 55	Indice de vitesse avant V	Indice de vitesse arrière V
Largeur avant 205	Largeur arrière 205	Roue de secours tôle
Climatisation	Climatisation réfrigérant 1234YF	Accoudoir central avant
Essence	999 cm3	1.00 litre
81 kw	110 ch	Alternateur 140 Ampères

Métallisée vernissée
Rétroviseur gauche chauffant
Rétroviseur droit jour/nuit automatique

Siège avant gauche chauffant
Sièges avant réglable en hauteur
Fixations Isofix aux places arrières
Volant multifonction
Caméra avant
Equipement Stop & Start

Appel de secours
Vitres de custode teintées foncées
Airbag latéraux avant
Témoin d'oubli de ceinture avant
Freinage d'urgence assistée autonome (urbain)
caméra de marche arrière (Type 2)

pare-brise athermique
porte-lunettes
pré-équipement pour attache-remorque
services Online

écran pare-chocs av/ar gris platine

Freins avant à disques
Rétroviseur droit chauffant
Rétroviseurs peints

Sièges avant chauffants
3ème appui-tête arrière
Garnitures tissu
Aide au stationnement avant
Régulateur et limiteur de vitesse
Affichage lecture des panneaux de signalisation

Lunette arrière teintée foncée
détecteur de pluie essuie-vitre
Airbag rideaux avant
Témoin d'oubli de ceinture arrière
vide-poches dans le coffre

insonorisation étendué

App-Connect
protection sous mécanique
réservoir à charbon actif (EVAP)
radio avec récepteur numérique

Freins arrière à disques
Rétroviseur gauche jour/nuit automatique
Rétroviseur intérieur jour/nuit automatique
Siège avant gauche réglable en hauteur
Fixations Isofix siège passager avant
Volant cuir
Aide au stationnement arrière
Régulateur automatique de la distance
Lève-vitres arrière électriques

Vitres portes arrière teintées foncées
Fixotoit noir
Airbag rideaux arrière
Protection piéton
depuis 02.23

grille de calandre avec moulures chromées
pare-pluie sur la porte du côté conducteur
combiné instruments Digital
norme anti-pollution Euro 6 AP
entretien à intervalle flexible (Long Life) QI6

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	3 mm	Vredestein	205551795v	All-seasons	Aluminium	×
Front right	3 mm	Vredestein	205551795v	All-seasons	Aluminium	×
Rear left	3 mm	Vredestein	205551795v	All-seasons	Aluminium	×
Rear right	3 mm	Vredestein	205551795v	All-seasons	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Outside rear-view mirror housing L	
4	Door FL	Bad repair
7	Inner door sill FR	
8	Alloy rim FR	

Total: 4

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Instrumentpanelboard	Damaged	✓	×	×
3	Windscreen	Stone chip(s)	✓	×	×

#	Location	Damage type	Renta®	Repaired	Already invoiced
5	Door RR	Stone chip(s)	✓	✗	✗
6	Outside rear-view mirror housing R	Residue	✓	✗	✗

Total: 4

DAMAGES DETAILS

2 - Outside rear-view mirror housing L




4 - Door FL - Bad repair





7 - Inner door sill FR




8 - Alloy rim FR






1 - Instrumentpanelboard - Damaged - Renta®




3 - Windscreen - Stone chip(s) - Renta®




5 - Door RR - Stone chip(s) - Renta®





6 - Outside rear-view mirror housing R - Residue - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert	Customer
23/10/2026 13:44	23/10/2026 13:44
	Useless