MACADAM









DACIA DUSTER: FY-551-MV

Vinnumber:	**VF1HJD40666939756**	Versionname:	**DACIA DUSTER Confort Blue dCi 115 4x4 E6U VP [5P] bvm 6-115CH-6cv (SUV)**
First Registrationdate:	**12/04/2021**	Fiscalpower:	
Expertise Mileage:	**112632**	Power Kw:	**85**
Bodytype:	**SUV**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Paint type	**Opaque**
Transmission:	**4 Wheel-drive**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Tow bar	
Number keys remote	**1**	Radio	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Seat cover lining	**Lining Other**
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**215/65/16/98 T**			
	Fr.L.	**BF Goodrich: 50%**	Fr.R.	**BF Goodrich: 55%**
	Re.L.	**BF Goodrich: 30%**	Re.R.	**BF Goodrich: 35%**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**4.5**
Tyre profile depth RL	**6.2**
Tyre profile depth RR	**5.8**
Tyre size FL	**215/65 R 16 98 T**
Tyre size FR	**215/65 R 16 98 T**
Tyre size RL	**215/65 R 16 98 T**
Tyre size RR	**215/65 R 16 98 T**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**2485**
Tyre make FR	**2485**
Tyre make RL	**2485**
Tyre make RR	**2485**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Remote ignition key, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Alloy rim RR, Scratch(es), Repair/replace (lump sum)




Alloy rim FR, Scratch(es), Repair/replace (lump sum)




Tyre FR, Deformed / Strained, Replace




Wing FL, Dent(s), Acceptable




Wing RL, Dent(s), Acceptable




Door RL, Dent(s), Repair and paint (complete)




Bumper moulding F, Chemical polution, Polish




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)




Door RR, Dent(s) and scratch(es), Repair and paint (complete)




Outer sill R, Scratch(es), Paint






Reflector, Broken, Replace




Bodywork, Not original part, Sticker removal small



ALPHABET

Historique Maintenance

Immatriculation: **FY-551-MV** Date de 1ère immatriculation: **12/04/2021**

Modèle: **Dacia DUSTER Confort Blue dCi 115 4x4 E6U VP [5P] bvm 6-115CH-6cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
22/06/2026	106.937	ROQUEMAURE AUTOMOBILES	BATTERIE RPLT
17/02/2026	100.093	ROQUEMAURE AUTOMOBILES	LIQUIDE DE REFROIDISSEMENT RPLT
			REVISION ET CLIM
			BALAIS ESSUIE GLACE AV
			RECYCLAGE
12/09/2025	90.591	ROQUEMAURE AUTOMOBILES	COLLECTEUR ECHAPPEMENT RPLT
			DISQUES PLAQUETTES AV RPLT
			ADBLUE
			REVISION ET CLIM ET AIR ET CARBURANT
08/04/2025	81.873	CONTROLE SECURITE ANGLOIS	CONTROLE TECHNIQUE
04/03/2025	79.443	ROQUEMAURE AUTOMOBILES	ESSAI
			CAPTEURS DIVERS RPLT
			DIVERS ELEC
			SONDE LAMBDA RPLT
10/02/2025	78.138	ROQUEMAURE AUTOMOBILES	DIVERS ELEC
			DIAG
			TUYAU ECHAPPEMENT RPLT
			DIVERS ECHAPPEMENT
			ESSAI
06/08/2024	68.668	ROQUEMAURE AUTOMOBILES	RECYCLAGE
			LIQUIDE DE FREIN
			REVISION ET CLIM
31/01/2024	57.678	ROQUEMAURE AUTOMOBILES	SERENITE
			BALAIS ESSUIE GLACE AV AR
			LIQUIDE DE FREIN
01/06/2023	45.341	ROQUEMAURE AUTOMOBILES	PLAQUETTES AV RPLT
			FILTRE A CARBURANT CTRL
			REVISION
06/03/2023	41.364	ROQUEMAURE AUTOMOBILES	DIVERS ECHAPPEMENT
			BALAIS ESSUIE GLACE AV AR
			SERENITE