

INSPECTION REPORT


End of contract

GENERAL INFO

File	312916
License plate	2CDJ675
Vehicle identification number	NMTK53BX90R090752
Dossier	2022 061 071
Make	Toyota C-HR 2.0 Hybrid C-Hic B
Mileage	95302
First registration	13/06/2022
client availability date	12/05/2026
inspectionDate	28/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
281	Bumper Rear / Trim Left / Replace	N
136	Bumper Rear // Polish	N
186	Wing Rear Right // Polish	N
187	Wing Rear Right / Trim / Replace	N
14	Bumper Front // Repair & Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
103	Door Rear Left // Painting	N
116	Wing Rear Left // Polish	N
84	Door Front Left // Repair & Painting	N
190	Door Rear Right // Smart Repair Small	Y
213	Door Front Right // Painting	Y
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
634	Rear Left Door Interior Coating // Replace Completely	N
644	Rear Right Door Interior Coating // Replace Completely	N

Damage Pictures



See External Expertise-



Door Front Right // Painting-scratch



Door Rear Right // Smart Repair Small-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Rear Right Door Interior Coating // Replace Completely-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Door Front Left // Repair & Painting-scratch + dent



Bumper Rear / Trim Left / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wing Rear Left // Polish-scratch



Door Rear Left // Painting-scratch



Wing Rear Right // Polish-scratch



Wing Rear Right / Trim / Replace-scratch



Bumper Rear // Polish-scratch



Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Lower Cover Not Painted / Replace-scratch