



Volkswagen Tiguan (KKL): 2CCN256

Vinnnumber:	WVGZZZ5NZNW044358	Versionname:	Tiguan Life Business 1.5TSi 150pk/cv 5p
First Registrationdate:	3/06/2022	Fiscalpower:	
Expertise Mileage:	85075	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	in 22700 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/65/17/99 V			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/65 R 17 99 V
Tyre size FR				215/65 R 17 99 V
Tyre size RL				215/65 R 17 99 V
Tyre size RR				215/65 R 17 99 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Interior, Dirty, Cleaning			





Door panel RR, Scratch(es), Acceptable



Bonnet, Scratch(es), Acceptable



Windscreen, Stone chip(s), Acceptable



Door RL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Boot cover, Broken, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Spot repair



Wheel aperture RR, Scratch(es), Spot repair




Door FR, Dent(s), Paintless dent repair



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Wing trim RR, Scratch(es), Acceptable



Tyres, Not original part, Check



Roof, Dent(s), Paintless dent repair



Kenteken	2CCN256
Merk Model	Volkswagen Tiguan Life Business 1.5TSi 150pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	6/3/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/22/26	77,749	batterij	Vervangen
5/22/26	77,749	bougie	Vervangen
5/22/26	77,749	brandblusapparaat	Vervangen
5/22/26	77,749	Inspectie met olie vervanging (vast in	Uitvoeren
5/22/26	77,749	klein materiaal	
5/22/26	77,749	koelwater vloeistof	Bijvullen/-laden
5/22/26	77,749	luchtfilter	Vervangen
5/22/26	77,749	nazicht technische keuring	Uitvoeren
5/22/26	77,749	remblokken achter	Vervangen
5/22/26	77,749	ruitenswisserrubber achter	Vervangen
5/22/26	77,749	ruitenswisserrubber vooraan	Vervangen
5/22/26	77,749	ruitenswisservloeistof	Bijvullen/-laden
12/9/24	48,206	controle niveaus	Uitvoeren
5/8/24	32,961	airco systeem reiniging	Uitvoeren
5/8/24	32,961	batterij	Vervangen
5/8/24	32,961	Inspectie met olie vervanging (vast in	Uitvoeren
5/8/24	32,961	klein materiaal	Uitvoeren
5/8/24	32,961	luchtfilter interieur	Vervangen
5/8/24	32,961	remvloeistof	Vervangen
5/8/24	32,961	ruitenswisserrubber achter	Vervangen
5/8/24	32,961	ruitenswisserrubber vooraan	Vervangen
5/8/24	32,961	ruitenswisservloeistof	Bijvullen/-laden